


PROBLEM SUMMARY

INTERSTITIAL Machine Id B53419 - POWER UNIT PU-H6 BLANCHER 1


Component

Hydraulic System

PETRO CANADA PURITY FG AW HYDRAULIC 46 (30 GAL)



COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status			ATTENTION	ATTENTION	ABNORMAL			
Particles >4µm	ASTM D7647	>5000	A 8126	△ 9798	<u>12191</u>			
Oil Cleanliness	ISO 4406 (c)	>19/17/14	20/16/11	20/16/10	2 1/16/10			

Customer Id: PRODUB Sample No.: WC0842531 Lab Number: 06007622 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

03 Aug 2023 Diag: Don Baldridge

ISO



No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



25 Apr 2023 Diag: Doug Bogart

ISO



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



01 Feb 2022 Diag: Angela Borella

ISO



No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of silt (particulates < 6 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT

INTERSTITIAL B53419 - POWER UNIT PU-H6 BLANCHER 1

Hydraulic System

PETRO CANADA PURITY FG AW HYDRAULIC 46 (30 GAL)





DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

2010 Julio 3 Julio Britan May 2016 Britan Br						
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0842531	WC0838782	WC0775030
Sample Date		Client Info		13 Nov 2023	03 Aug 2023	25 Apr 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				ATTENTION	ATTENTION	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	25	28	28
Chromium	ppm	ASTM D5185m	>20	2	4	3
Nickel	ppm	ASTM D5185m	>20	1	1	<1
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	1	3	3
Lead	ppm	ASTM D5185m	>20	0	0	0
Copper	ppm	ASTM D5185m	>20	10	12	11
Tin	ppm	ASTM D5185m	>20	0	0	0
Antimony	ppm	ASTM D5185m				
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	<1	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	<1
Manganese	ppm	ASTM D5185m		0	<1	<1
Magnesium	ppm	ASTM D5185m		0	2	0
Calcium	ppm	ASTM D5185m		5	8	<1
Phosphorus	ppm	ASTM D5185m		347	404	419
Zinc	ppm	ASTM D5185m		84	93	85
Sulfur	ppm	ASTM D5185m		954	1239	857
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	1	2	1
Sodium	ppm	ASTM D5185m		3	5	3
Potassium	ppm	ASTM D5185m	>20	0	<1	0
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	8126	△ 9798	<u>▲</u> 12191
Particles >6µm		ASTM D7647	>1300	568	323	478
Particles >14µm		ASTM D7647	>160	19	8	10
Particles >21µm		ASTM D7647	>40	4	1	3
Particles >38µm		ASTM D7647	>10	0	0	0
Particles >71µm		ASTM D7647	>3	0	0	0
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>^</u> 20/16/11	2 0/16/10	1 21/16/10
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.26	0.25	0.28	0.28



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
ELLID DDODEDT	and the sale	Uses It flags and		Internal	la la tarre o	
FLUID PROPERTIES		method	limit/base	current	history1	history2

8 150k

Visc @ 40°C cSt ASTM D445 45.36 44.6 44.7 44.4

SAMPLE IMAGES

method


limit/base current history1


history2


Color

Bottom













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number**

: 06007622

: WC0842531 : 10741384

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Nov 2023 Diagnosed : 16 Nov 2023

: Don Baldridge Diagnostician

Test Package : IND 2 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

PROGRESSIVE PROCESSING INC

1205 CHAVENELLE CT DUBUQUE, IA US 52002

Contact: BLAINE PURDY

bepurdy@hormel.com T: (563)557-4500

F: (563)557-4508