

URC

## **PROBLEM SUMMARY**


## **ROV** Hydraulic Compensator

**Hydraulic System** 

SHELL AEROSHELL 41 (--- GAL)

# Sample Rating Trend ISO

## **COMPONENT CONDITION SUMMARY**



## RECOMMENDATION

No corrective action is recommended at this time. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status			ATTENTION							
Particles >4µm	ASTM D7647	>10000	<b>19265</b>							
Oil Cleanliness	ISO 4406 (c)	>20/18/15	<u> </u>							
PrtFilter				no image	no image					

Customer Id: OCESAN Sample No.: PH0000923 Lab Number: 06007954 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

## RECOMMENDED ACTIONS

There are no recommended actions for this sample.

## HISTORICAL DIAGNOSIS



## **OIL ANALYSIS REPORT**

SAMPLE INFORMATION method

## URC. **ROV** Hydraulic Compensator

**Hydraulic System** 

SHELL AEROSHELL 41 (--- GAL)

## Sample Rating Trend ISO

history1

## **DIAGNOSIS**

### Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

All component wear rates are normal.


## Contamination

There is a moderate amount of silt (particulates < 14 microns in size) present in the oil.

### **Fluid Condition**


The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in

Sample Number		Client Info		PH0000923		
Sample Date		Client Info		08 Nov 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Not Changd		
Sample Status				ATTENTION		
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	3		
Chromium	ppm	ASTM D5185m	>20	0		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>20	<1		
Lead	ppm	ASTM D5185m	>20	0		
Copper	ppm		>20	7		
Tin	ppm	ASTM D5185m	>20	0		
Vanadium	ppm	ASTM D5185m	720	0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	U	0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		6		
Phosphorus		ASTM D5185m		479		
Zinc	ppm	ASTM D5185m		13		
	ppm					
Sulfur	ppm	ASTM D5185m		175		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1		
Sodium	ppm	ASTM D5185m		<1		
Potassium	ppm	ASTM D5185m	>20	0		
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647	>10000	<u> </u>		
Particles >6µm		ASTM D7647	>2500	1864		
Particles >14μm		ASTM D7647	>320	108		
Particles >21µm		ASTM D7647	>80	29		
Particles >38µm		ASTM D7647	>20	1		
Particles >71μm		ASTM D7647	>4	0		
Oil Cleanliness		ISO 4406 (c)	>20/18/15	<u>^</u> 21/18/14		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.07	0.042		





## **OIL ANALYSIS REPORT**







Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** 

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : PH0000923

: 06007954 : 10741716

Received : 14 Nov 2023 Diagnosed : 28 Nov 2023

: Angela Borella Diagnostician Test Package : PLANT ( Additional Tests: PrtFilter )

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

**OCEANEERING INTERNATIONAL INC** 

497 BLDG SAN DIEGO, CA US 92135

Contact: CALVIN BROWN CBROWN4@OCEANEERING.NET

T: (404)642-8815

F: