

PROBLEM SUMMARY

Sample Rating Trend

WEAR




Machine Id


Component

Hydraulic System

NOT GIVEN (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

PROPUENTATION TEXT PECULINA								
PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Copper	ppm	ASTM D5185m	>20	49				
Particles >4μm		ASTM D7647	>5000	72873				
Particles >6µm		ASTM D7647	>1300	4 3448				
Oil Cleanliness		ISO 4406 (c)	>19/17/14	23/19/13				

Customer Id: MEILEW Sample No.: KFS06008290 Lab Number: 06008290 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net


To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component if applicable.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT



Machine Id

Component **Hydraulic System**

NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.

The copper level is abnormal. All other component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.


				Nov2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KFS06008290		
Sample Date		Client Info		14 Nov 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	2		
Chromium	ppm	ASTM D5185m	>20	0		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>20	3		
Lead	ppm	ASTM D5185m	>20	3		
Copper	ppm	ASTM D5185m	>20	4 9		
Tin	ppm	ASTM D5185m	>20	0		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		30		
Phosphorus	ppm	ASTM D5185m		335		
Zinc	ppm	ASTM D5185m		320		
Sulfur	ppm	ASTM D5185m		3112		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	3		
Sodium	ppm	ASTM D5185m		<1		
Potassium	ppm	ASTM D5185m	>20	<1		
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	72873		
Particles >6µm		ASTM D7647	>1300	4 3448		
Particles >14µm		ASTM D7647	>160	50		
Particles >21µm		ASTM D7647	>40	17		
Particles >38µm		ASTM D7647	>10	1		
Particles >71µm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	23/19/13		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	та КОЦ/а	VCTM DOUVE		0.10		

Acid Number (AN) mg KOH/g ASTM D8045

0.19



OIL ANALYSIS REPORT







Certificate L2367

Sample No. Lab Number **Unique Number** Test Package : PLANT

: 06008290

: KFS06008290 : 10742052

Received : 15 Nov 2023 Diagnosed : 17 Nov 2023 : Don Baldridge Diagnostician

1041 VETERANS DR LEWISBURG, TN US 37091

Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: