

PROBLEM SUMMARY

Sample Rating Trend

WATER

Machine Id


KAESER BSD 50 5885077 (S/N 1687)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

There is too much water present in this sample to perform a particle count. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.

PROBLEMATIC TEST RESULTS											
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL					
Water	%	ASTM D6304	>0.05	△ 0.495	△ 0.242	0.037					
ppm Water	ppm	ASTM D6304	>500	4950	<u>4</u> 2420	370					
Emulsified Water	scalar	*Visual	>0.05	0.2%	0.2%	0.2%					

Customer Id: AACELK Sample No.: KC06010799 Lab Number: 06010799 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

02 Jun 2023 Diag: Angela Borella

WATER



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We recommend an early resample in 500 hours to monitor this condition. We advise that you stop the unit and follow the water drain-off procedure for this component. We were unable to perform a particle count due to a high concentration of particles present in this sample. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid.



30 Nov 2022 Diag: Doug Bogart

VIS DEBRIS



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



23 Jul 2021 Diag: Angela Borella

VIS DEBRIS



The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

KAESER BSD 50 5885077 (S/N 1687)

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

There is too much water present in this sample to perform a particle count. We advise that you stop the unit and follow the water drain-off procedure for this component. We recommend an early resample in 500 hours to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of water present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFORM	NATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KC06010799	KC05865690	KC104217
Sample Date		Client Info		09 Nov 2023	02 Jun 2023	30 Nov 2022
Machine Age	hrs	Client Info		31093	1682	26162
Oil Age	hrs	Client Info		0	0	1194
Oil Changed		Client Info		N/A	N/A	Not Changd
Sample Status				ABNORMAL	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	0	<1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	0	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>10	0	<1	<1
Lead	ppm	ASTM D5185m	>10	0	0	0
Copper	ppm	ASTM D5185m	>50	6	7	10
Tin	ppm	ASTM D5185m	>10	0	0	0
Antimony	ppm	ASTM D5185m				
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m	90	0	6	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	<1	0
Magnesium	ppm	ASTM D5185m	90	0	3	0
Calcium	ppm	ASTM D5185m	2	0	3	0
Phosphorus	ppm	ASTM D5185m		0	6	7
Zinc	ppm	ASTM D5185m		<1	15	0
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	0	<1	0
Sodium	ppm	ASTM D5185m		2	<1	0
Potassium	ppm	ASTM D5185m	>20	0	0	0
Water	%	ASTM D6304	>0.05	△ 0.495	△ 0.242	0.037
ppm Water	ppm	ASTM D6304	>500	4950	<u>42420</u>	370
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2

0.38

Acid Number (AN)

mg KOH/g ASTM D8045 0.4


0.41


0.40




OIL ANALYSIS REPORT













Certificate L2367

Laboratory Sample No. Lab Number **Unique Number** Test Package

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : KC06010799 : 06010799 : 10749943

Received : 17 Nov 2023 Diagnosed : 20 Nov 2023 Diagnostician : Don Baldridge

AACOA - BONNELL ALUMINUM 2551 CR 10 WEST ELKHART, IN

US 46514 Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: IND 2

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: