

# **FUEL REPORT**

## Sample Rating Trend



## CUMMINS/ONAN GLEN ISLAND 1 Component

**Diesel Fuel** Fluid NOT GIVEN (4 GAL)


## Recommendation

This is a baseline read-out on the submitted sample.

### Corrosion

All metal levels are normal indicating no corrosion in the system.

		Nov2015	3 Dec2021	Oct2022 No	v2023	
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number Sample Date Machine Age Sample Status	hrs	Client Info Client Info Client Info		WC0878327 20 Nov 2023 0 NORMAL	WC0748979 28 Oct 2022 593 NORMAL	WC0612335 03 Dec 2021 593 NORMAL
SULFUR CONTENT		method	limit/base	current	history1	history2
Sulfur	ppm	ASTM D5185m		0	12	0
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon Sodium Potassium	ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m	<1.0 <0.1 <0.1	<1 1 0	0 0 1	0 0 0
HEAVY METALS		method	limit/base	current	history1	history2
Aluminum Nickel Lead	ppm ppm ppm	ASTM D5185m ASTM D5185m ASTM D5185m	<0.1 <0.1 <0.1	0 0 0	<1 0 0	0 0
Vanadium Iron	ppm ppm	ASTM D5185m ASTM D5185m	<0.1 <0.1	0	0	0
Calcium Magnesium	ppm ppm	ASTM D5185m ASTM D5185m	<0.1 <0.1	0	0	0
Phosphorus Zinc	ppm ppm	ASTM D5185m ASTM D5185m	<0.1 <0.1	0 0	3 <1	0 0
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color						
Bottom						





# **FUEL REPORT**



Report Id: GENNEW [WUSCAR] 06014391 (Generated: 11/30/2023 01:10:40) Rev: 1

3017 RT 9W NEW WINDSOR, NY US 12553 Contact: JOE SAYEGH joe@gentechltd.com T: (845)568-0500 F: (845)568-3073

: 21 Nov 2023

: 27 Nov 2023

Diagnostician : Jonathan Hester

Received

Diagnosed

GEN TECH LTD

Submitted By: ?

Page 2 of 2