

FUEL REPORT

Machine Id Westchester def weaver st pump 1990988778 Component

Diesel Fuel NOT GIVEN (--- GAL)


DIAGNOSIS

Recommendation

This is a baseline read-out on the submitted sample.

Corrosion

All metal levels are normal indicating no corrosion in the system.






SAMPLE INFORMATION method WC0878335 WC0699344 WC0612495 Client Info Sample Number 30 Nov 2021 Sample Date Client Info 20 Nov 2023 14 Nov 2022 0 0 Machine Age hrs **Client Info** 504 Sample Status NORMAL NORMAL NORMAL 0 6 9 Sulfur ASTM D5185m ppm CONTAMINANTS Silicon ppm ASTM D5185m <1.0 2 0 0 <0.1 0 0 Sodium ppm ASTM D5185m 1 Potassium ASTM D5185m <0.1 0 2 0 ppm 0 Aluminum ppm ASTM D5185m < 0.1 0 <1 Nickel ASTM D5185m <0.1 0 0 0 ppm Lead ppm ASTM D5185m < 0.1 0 0 0 Vanadium 0 0 ASTM D5185m <0.1 0 ppm Iron ASTM D5185m < 0.1 2 2 0 ppm 0 0 Calcium ASTM D5185m <0.1 ppm <1 Magnesium ppm ASTM D5185m < 0.1 0 0 0 Phosphorus ASTM D5185m <0.1 0 3 0 ppm ASTM D5185m <0.1 0 0 0 Zinc ppm SAMPLE IMAGES


Color


Bottom






FUEL REPORT







3017 RT 9W NEW WINDSOR, NY US 12553 Contact: JOE SAYEGH joe@gentechltd.com T: (845)568-0500 F: (845)568-3073

Submitted By: ?

Page 2 of 2