

PROBLEM SUMMARY

070-HOMO-0-06

Component Gearbox

NOT GIVEN (--- GAL)

Sample Rating Trend **WATER**

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

We advise that you check for the source of water entry. We advise that you follow the water drain-off procedure for this component. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Free Water	scalar	*Visual		10.0				

Customer Id: JACHUT Sample No.: USP245336 Lab Number: 06014552 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Water Drain-off			?	We advise that you follow the water drain-off procedure for this component.			
Check Water Access			?	We advise that you check for the source of water entry.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend





070-HOMO-0-06

Component

Gearbox

NOT GIVEN (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check for the source of water entry. We advise that you follow the water drain-off procedure for this component. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

Free water present. The amount and size of particulates present in the system are acceptable.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

				Oct2023		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		USP245336		
Sample Date		Client Info		23 Oct 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	11		
Chromium	ppm	ASTM D5185m	>15	<1		
Nickel	ppm	ASTM D5185m	>15	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	2		
Lead	ppm	ASTM D5185m	>100	1		
Copper	ppm	ASTM D5185m		3		
Tin	ppm	ASTM D5185m	>25	<1		
Vanadium	ppm	ASTM D5185m	720	0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES	ррш	method	limit/base	current	history1	history2
			IIIIIIVDase			,
Boron	ppm	ASTM D5185m		7		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		2		
Calcium	ppm	ASTM D5185m		4		
Phosphorus	ppm	ASTM D5185m		330		
Zinc	ppm	ASTM D5185m		8		
Sulfur	ppm	ASTM D5185m		9935		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	7		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	3		
Water	%	ASTM D6304	>0.2	0.074		
ppm Water	ppm	ASTM D6304	>2000	740		
FLUID CLEANLIN	ESS	method	limit/base	current	history1	history2
Particles >4μm		ASTM D7647		7779		
Particles >6μm		ASTM D7647	>2500	992		
Particles >14μm		ASTM D7647	>320	16		
Particles >21µm		ASTM D7647	>80	2		
Particles >38µm		ASTM D7647	>20	0		
Particles >71µm		ASTM D7647	>4	0		
Oil Cleanliness		ISO 4406 (c)	>/18/15	20/17/11		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.63		



OIL ANALYSIS REPORT





Certificate L2367

Sample No. Lab Number **Unique Number**

Test Package

: USP245336 : 06014552

: 10753696

Received Diagnosed

: 24 Nov 2023 : Doug Bogart

: 21 Nov 2023

Diagnostician

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: IND 2

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

2600 E 4TH HUTCHINSON, KS US 67501

Contact: Jason Stanley jason.stanley@kroger.com

T: (620)694-6922

F: (620)663-5135

Contact/Location: Jason Stanley - JACHUT