

PROBLEM SUMMARY

Sample Rating Trend

WATER




SULLAIR TS-32 (S/N 21069-FGE)

Air Compressor

USPI AIR 46 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

PROBLEMATIC	PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL				
Water	%	ASTM D6304	>0.2	△ 0.712				
ppm Water	ppm	ASTM D6304	>2000	7129				
Debris	scalar	*Visual	NONE	▲ MODER				

Customer Id: TYSTRA Sample No.: USPM31383 Lab Number: 06016441 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Doug Bogart +1 (800)237-1369 x4016 dougb@wearcheckusa.com


To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			
Alert			?	We were unable to perform a particle count due to a high concentration of particles present in this sample.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT



WATER

SULLAIR TS-32 (S/N 21069-FGE)

Air Compressor

USPI AIR 46 (--- GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample.

Wear

All component wear rates are normal.

Contamination

There is a moderate concentration of water present in the oil. Moderate concentration of visible dirt/debris present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFORM	ΙΔΤΙΩΝΙ	method	limit/base	current	history1	history2
	I/ (TIOI)		IIIIIIIIIIIIII		,	,
Sample Number		Client Info		USPM31383		
Sample Date	,	Client Info		26 Oct 2023		
Machine Age	hrs	Client Info		44502		
Oil Age	hrs	Client Info		1604		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	4		
Chromium	ppm	ASTM D5185m	>4	<1		
Nickel	ppm	ASTM D5185m	>4	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>10	0		
Lead	ppm	ASTM D5185m	>20	0		
Copper	ppm	ASTM D5185m	>40	<1		
Tin	ppm	ASTM D5185m	>5	<1		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	0		
Barium	ppm	ASTM D5185m	0	513		
Molybdenum	ppm	ASTM D5185m	0	<1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m	0	1		
Calcium	ppm	ASTM D5185m	0	3		
Phosphorus	ppm	ASTM D5185m	1	0		
Zinc	ppm	ASTM D5185m	0	0		
Sulfur	ppm	ASTM D5185m	0	200		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	1		
Sodium	ppm	ASTM D5185m		21		
Potassium	ppm	ASTM D5185m	>20	3		
Water	%	ASTM D6304	>0.2	△ 0.712		
ppm Water	ppm	ASTM D6304	>2000	<u>^</u> 7129		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2


0.172

Acid Number (AN)

mg KOH/g ASTM D8045 0.05



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number Unique Number

: 06016441

: USPM31383 : 10755585 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 24 Nov 2023 : 27 Nov 2023 : Doug Bogart Diagnostician

SARA LEE - TRAVERSE CITY 2314 SYBRANT RD TRAVERSE CITY, MI US 49684

Contact:

T:

F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)