

PROBLEM SUMMARY

Sample Rating Trend

DEGRADATION



GM Seattle Off Raod Shop
[GM Seattle Off Raod Shop] 26-222

Diesel Engine

SHELL 15W40 (--- GAL)





COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status				ABNORMAL	NORMAL	NORMAL	
Base Number (BN)	mg KOH/g	ASTM D2896		△ 0.3	6.1	7.5	

Customer Id: GARSEA Sample No.: PE0002298 Lab Number: 06026064 Test Package: CONST

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

Action	Status	Date	Done By	Description
Change Fluid			?	Oil and filter change at the time of sampling has been noted.
Change Filter			?	Oil and filter change at the time of sampling has been noted.

HISTORICAL DIAGNOSIS

13 Feb 2023 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.



20 Oct 2022 Diag: Don Baldridge

NORMAL



Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

view report

11 Apr 2022 Diag: Wes Davis

NORMAL



Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT


Sample Rating Trend

DEGRADATION



GM Seattle Off Raod Shop [GM Seattle Off Raod Shop] 26-222

Diesel Engine
Fluid
SHELL 15W40 (--- GAL)





DIAGNOSIS

Recommendation

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil


Fluid Condition


The BN level is low.

			18 Oct2018 Mar2019 J			
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		PE0002298	PE0001062	PE0000384
Sample Date		Client Info		30 Nov 2023	13 Feb 2023	20 Oct 2022
Machine Age	hrs	Client Info		7634	6848	6366
Oil Age	hrs	Client Info		786	416	717
Oil Changed		Client Info		Changed	Changed	Not Changd
Sample Status				ABNORMAL	NORMAL	NORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Fuel		WC Method	>5	<1.0	<1.0	<1.0
Water		WC Method	>0.2	NEG	NEG	NEG
Glycol		WC Method		NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	57	43	32
Chromium	ppm	ASTM D5185m	>20	3	2	1
Nickel	ppm	ASTM D5185m	>2	<1	0	0
Titanium	ppm	ASTM D5185m	>2	<1	<1	<1
Silver	ppm	ASTM D5185m	>2	0	0	0
Aluminum	ppm	ASTM D5185m	>25	8	8	6
Lead	ppm	ASTM D5185m	>40	31	12	6
Copper	ppm	ASTM D5185m	>330	8	7	7
Tin	ppm	ASTM D5185m	>15	2	<1	<1
Antimony	ppm	ASTM D5185m				
Vanadium	ppm	ASTM D5185m		<1	0	<1
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		10	10	13
Barium	ppm	ASTM D5185m		0	0	2
Molybdenum	ppm	ASTM D5185m		37	35	37
Manganese	ppm	ASTM D5185m		<1	<1	<1
Magnesium	ppm	ASTM D5185m		506	432	469
Calcium	ppm	ASTM D5185m		1867	1876	1998
Phosphorus	ppm	ASTM D5185m		978	942	981
Zinc	ppm	ASTM D5185m		1223	1169	1234
Sulfur	ppm	ASTM D5185m		2924	3315	3800
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	10	12	6
Sodium	ppm	ASTM D5185m	>150	4	3	4
Potassium	ppm	ASTM D5185m	>20	0	2	6
INFRA-RED		method	limit/base	current	history1	history2
Soot %	%	*ASTM D7844	>3	2.6	2.1	1.6
Nitration	Abs/cm	*ASTM D7624	>20	13.9	13.1	11.9
Sulfation	Abs/.1mm	*ASTM D7415	>30	29.4	27.8	25.5
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Oxidation	Abs/.1mm	*ASTM D7414	>25	21.9	20.1	18.4
Base Number (BN)	mg KOH/g	ASTM D2896	-	△ 0.3	6.1	7.5
= 1.00 · (2.14)					0	



OIL ANALYSIS REPORT







VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG


FLUID PROPE	7115	memod	iiiiii/base	current	riistory i	nistoryz
Visc @ 100°C	cSt	ASTM D445		14.1	13.9	13.9


GRAPHS

Ferrous Alloys













Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 10775855

: PE0002298 : 06026064

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 06 Dec 2023 : 07 Dec 2023

Diagnostician : Don Baldridge

Test Package : CONST (Additional Tests: FT-IR, ICP, KV100, SCREEN, TBN)

9125 10TH AVE SOUTH SEATTLE, WA US 98108 Contact: Jesse Patterson

Gary Merlino Construction - Off Road Shop

oilsamples@gmccinc.com T: 1(866)292-1303

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)