

PROBLEM SUMMARY

Sample Rating Trend

VISCOSITY




Machine Id 1 - REXROTH


Component

Hydraulic System

FLEET WING AW 68 (110 GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We recommend you service the filters on this component. Due to an abnormal test result it is recommended to contact Stauff Corp at (201)-444-7800 for help resolving the issue.

PROBLEMATIC TEST RESULTS								
Sample Status				ABNORMAL				
Particles >4µm		ASTM D7647	>5000	49210				
Particles >6µm		ASTM D7647	>1300	△ 6782				
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>23/20/14</u>				
Visc @ 40°C	cSt	ASTM D445		<u> </u>				

Customer Id: TECTAMFL Sample No.: ST43261 Lab Number: 06029381 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net


To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Filter			?	We recommend you service the filters on this component.			
Contact Required			?	Due to an abnormal test result it is recommended to contact Stauff Corp at (201)-444-7800 for help resolving the issue.			

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT



VISCOSITY

Machine Id

1 - REXROTH

Component

Hydraulic System

FLEET WING AW 68 (110 GAL)

DIAGNOSIS

Recommendation

We recommend you service the filters on this component. Due to an abnormal test result it is recommended to contact Stauff Corp at (201)-444-7800 for help resolving the issue.

Wear

All component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 14 microns in size) present in the oil.


Fluid Condition

The oil viscosity is lower than normal. The AN level is acceptable for this fluid.

				Dec2023		
OALADI E INICODA	44 TION					
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		ST43261		
Sample Date		Client Info		02 Dec 2023		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>40	3		
Chromium	ppm	ASTM D5185m	>4	<1		
Nickel	ppm	ASTM D5185m	>20	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>4	2		
Lead	ppm	ASTM D5185m	>10	0		
Copper	ppm	ASTM D5185m	>60	<1		
Tin	ppm	ASTM D5185m	>4	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		102		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		15		
Calcium	ppm	ASTM D5185m		2946		
Phosphorus	ppm	ASTM D5185m		1005		
Zinc	ppm	ASTM D5185m		1259		
Sulfur		ASTM D5185m		4670		
	ppm					
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>20	14		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	1		
Water	%	ASTM D6304	>0.05	0.022		
ppm Water	ppm	ASTM D6304	>500	225		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<u>49210</u>		
Particles >6µm		ASTM D7647	>1300	<u> </u>		
Particles >14μm		ASTM D7647	>160	124		
Particles >21µm		ASTM D7647	>40	28		
Particles >38μm		ASTM D7647	>10	2		
Particles >71μm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	23/20/14		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.88		



OIL ANALYSIS REPORT





Certificate L2367

Sample No. Lab Number **Unique Number**

: ST43261 : 06029381

: 10779172 Test Package : IND 2 (Additional Tests: KF)

Received : 08 Dec 2023 : 12 Dec 2023 Diagnosed Diagnostician : Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

8259 CAUSEWAY BLVD TAMPA, FL US 33619

> Contact: JOSH TRY jtry.tmi@outlook.com

> > T: F: (813)612-9385