

PROBLEM SUMMARY



Machine Id **B71698** Component **Gearbox**

Fluid PETRO CANADA (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

PROBLEMATIC TEST RESULTS

Sample Status			SEVERE	ATTENTION						
Particles >4µm	ASTM D7647	>10000	<u> </u>	10186						
Particles >6µm	ASTM D7647	>2500	<u> </u>	1363						
Particles >14µm	ASTM D7647	>320	93217	35						
Particles >21µm	ASTM D7647	>80	e 1380	8						
Oil Cleanliness	ISO 4406 (c)	>20/18/15	e 22/20/19	1 21/18/12						

Customer Id: HORAUS Sample No.: WC0880554 Lab Number: 06061008 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				
Resample			?	Resample in 30-45 days to monitor this situation.				
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.				
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.				
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.				
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				

HISTORICAL DIAGNOSIS

29 Sep 2023 Diag: Wes Davis





We recommend you service the filters on this component. Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend

ISO

Machine Id B71698 Component Gearbox Fluid PETRO CANADA (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. The system cleanliness code is much higher than the acceptable limit for the target ISO 4406 cleanliness code.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

			36pz0z3			
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0880554	WC0850211	
Sample Date		Client Info		05 Jan 2024	29 Sep 2023	
Machine Age	hrs	Client Info		0	0	
Oil Age	hrs	Client Info		0	0	
Oil Changed		Client Info		Not Changd	Not Changd	
Sample Status				SEVERE	ATTENTION	
CONTAMINATIO	N	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	
				-		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	<1	0	
Chromium	ppm	ASTM D5185m	>15	0	0	
Nickel	ppm	ASTM D5185m	>15	0	0	
Titanium	ppm	ASTM D5185m		0	0	
Silver	ppm	ASTM D5185m		0	0	
Aluminum	ppm	ASTM D5185m	>25	0	0	
Lead	ppm	ASTM D5185m	>100	0	0	
Copper	ppm	ASTM D5185m	>200	0	<1	
Tin	ppm	ASTM D5185m	>25	0	0	
Vanadium	ppm	ASTM D5185m		0	<1	
Cadmium	ppm	ASTM D5185m		0	0	
ADDITIVES		method	limit/base	current	history1	history2
	2222			0	0	
Boron	ppm	ASTM D5185m			0	
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0	0	
Manganese	ppm	ASTM D5185m		0	0	
Magnesium	ppm	ASTM D5185m		0	0	
Calcium	ppm	ASTM D5185m		0	0	
Phosphorus	ppm	ASTM D5185m		421	459	
Zinc	ppm	ASTM D5185m		0	0	
Sulfur	ppm	ASTM D5185m		1387	1656	
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	2	3	
Sodium	ppm	ASTM D5185m		<1	0	
Potassium	ppm	ASTM D5185m	>20	0	<1	
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>10000	A 24528	▲ 10186	
Particles >6µm		ASTM D7647	>2500	A 7661	1363	
Particles >14µm		ASTM D7647	>320	9 3217	35	
Particles >21µm		ASTM D7647	>80	1380	8	
Particles >38µm		ASTM D7647	>20	25	1	
Particles >71µm		ASTM D7647		0	0	
Oil Cleanliness		ISO 4406 (c)	>20/18/15	22/20/19	21/18/12	
		()		-		
FLUID DEGRADA		method	limit/base		history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.55	0.56	
6·22·47) Rev: 1				Contact/La	antion: DVANUC	WE - HOBALIS

Report Id: HORAUS [WUSCAR] 06061008 (Generated: 01/17/2024 16:22:47) Rev: 1

Contact/Location: RYAN LOWE - HORAUS



Acid Number

Viscosity @ 40°C

0.60

(B/HOX Bu 0.3

202

Pio 0.1

0.00

250


240


23


문 220 55

OIL ANALYSIS REPORT

VISUAL







 Certificate 12367
 Test Package
 : IND 2 (Additional Tests: PrtCount)

 To discuss this sample report, contact Customer Service at 1-800-237-1369.
 *

 * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Diagnosed

Diagnostician

: 17 Jan 2024

: Wes Davis

1101 NORTH MAIN ST AUSTIN, MN US 55912 Contact: RYAN LOWE rslowe@hormel.com T: (507)437-5674 F: (507)437-9805

Laboratory

Sample No.

Lab Number

Unique Number

:06061008

: 10832390