


PROBLEM SUMMARY

ROLL SHOP

44 Farrel Gearbox Lube 8100-014-0003


Component Gearbox

NOT GIVEN (--- GAL)





COMPONENT CONDITION SUMMARY



RECOMMENDATION

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

Customer Id: CONMUSAL Sample No.: KFS0004787 Lab Number: 06131995 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

PROBLEMATIC TEST RESULTS									
Sample Status			SEVERE	SEVERE	ABNORMAL				
Particles >4µm	ASTM D7647	>20000	311706	▲ 165435					
Particles >6µm	ASTM D7647	>5000	223052	1 13038					
Particles >14μm	ASTM D7647	>640	▲ 57020	1 21642					
Particles >21μm	ASTM D7647	>160	17227	▲ 5009					
Particles >38μm	ASTM D7647	>40	▲ 537	<u>113</u>					
Particles >71µm	ASTM D7647	>10	△ 36	14					
Oil Cleanliness	ISO 4406 (c)	>21/19/16	25/25/23	2 5/24/22					

RECOMMENDED ACTIONS Action **Status** Date Done By Description We advise that you perform a filter service, and use off-line filtration to Change Filter ? improve the cleanliness of the system fluid. Resample ? Resample in 30-45 days to monitor this situation. Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore ? Alert generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. Please specify the brand, type, and viscosity of the oil on your next sample, NOTE: Please ? Information Required provide information regarding reservoir capacity, filter type and micron rating with next sample. The air breather requires service. If unrated, we recommend that you replace with a **Check Breathers** ? suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We advise that you check all areas where contaminants can enter the **Check Dirt Access** ? We advise that you perform a filter service, and use off-line filtration to Filter Fluid ? improve the cleanliness of the system fluid.

HISTORICAL DIAGNOSIS

ISO



19 Dec 2023 Diag: Wes Davis

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.



30 Aug 2023 Diag: Don Baldridge

VIS DEBRIS



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid.



10 May 2023 Diag: Jonathan Hester

ISO



We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT

ROLL SHOP

44 Farrel Gearbox Lube 8100-014-0003

Gearbox

NOT GIVEN (--- GAL)





DIAGNOSIS

Recommendation

Little or no information is provided as to the component and lubricant being tested. Recommendations are therefore generic in nature and may not apply to the current application. Please forward information as to equipment type, reservoir capacity, lubricant type and any pertinent information to allow for a more accurate assessment. We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use offline filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample. Please specify the brand, type, and viscosity of the oil on your next sample.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

		May202	3 Aug2023	Dec2023 N	lar2024	
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		KFS0004787	KFS0004896	KFS0003614
Sample Date		Client Info		26 Mar 2024	19 Dec 2023	30 Aug 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	ABNORMAL
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	32	35	29
Chromium	ppm	ASTM D5185m	>15	0	<1	0
Nickel	ppm	ASTM D5185m	>15	<1	0	0
Titanium	ppm	ASTM D5185m		0	0	<1
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	<1	2	<1
Lead	ppm	ASTM D5185m	>100	0	0	<1
Copper	ppm	ASTM D5185m	>200	2	<1	<1
Tin	ppm	ASTM D5185m	>25	1	<1	<1
Vanadium	ppm	ASTM D5185m		0	0	<1
Cadmium	ppm	ASTM D5185m		0	0	<1
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		<1	<1	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		<1	0	<1
Magnesium	ppm	ASTM D5185m		<1	<1	4
Calcium	ppm	ASTM D5185m		8	5	1
Phosphorus	ppm	ASTM D5185m		182	303	251
Zinc	ppm	ASTM D5185m		214	261	307
Sulfur	ppm	ASTM D5185m		5413	5173	5417
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	5	6	4
Sodium	ppm	ASTM D5185m		3	0	2
Potassium	ppm	ASTM D5185m	>20	2	1	3
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	311706	▲ 165435	
Particles >6μm		ASTM D7647	>5000	223052	1 13038	
Particles >14μm		ASTM D7647	>640	▲ 57020	1 21642	
Particles >21µm		ASTM D7647	>160	17227	▲ 5009	
Particles >38µm		ASTM D7647	>40	▲ 537	<u> </u>	
Particles >71µm		ASTM D7647	>10	<u>▲</u> 36	14	
Oil Cleanliness		ISO 4406 (c)	>21/19/16	25/25/23	▲ 25/24/22	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.53	0.56	0.65



OIL ANALYSIS REPORT







Certificate L2367

Laboratory Sample No. Lab Number

: WearCheck USA - 501 Madison Ave., Cary, NC 27513

: KFS0004787 : 06131995

Unique Number: 10951460

Received **Tested** Diagnosed Test Package: IND 2 (Additional Tests: PrtCount)

: 28 Mar 2024 : 29 Mar 2024

: 29 Mar 2024 - Wes Davis

US 35661 Contact: Randy Nichols randall.nichols@constellium.com

To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (256)386-6956 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F:

CONSTELLIUM

4805 SECOND STREET

MUSCLE SHOALS, AL