

OIL ANALYSIS REPORT




Area [2402210123/1]

MCQUAY PATRICK HENRY BUILDING COMM OF VA CHILLER 1 (S/N STNU040310308)

Refrigeration Compressor

{not provided} (8 GAL)



DIAGNOSIS

Recommendation

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

There is a light concentration of water present in the


Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0812072	WC0430676	WC0487343
Sample Date		Client Info		11 Mar 2024	04 May 2022	25 Jan 2021
Machine Age	hrs	Client Info		0	51540	49140
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		Not Changd	Not Changd	N/A
Sample Status				MARGINAL	NORMAL	NORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>100	0	1	<1
Chromium	ppm	ASTM D5185m	>2	0	0	0
Nickel	ppm	ASTM D5185m		0	0	0
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m	>2	0	0	<1
Aluminum	ppm	ASTM D5185m	>50	0	0	0
Lead	ppm	ASTM D5185m	>2	0	<1	0
Copper	ppm	ASTM D5185m	>100	13	6	7
Tin	ppm	ASTM D5185m	>4	0	1	<1
Antimony	ppm	ASTM D5185m				0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	1
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	0
Magnesium	ppm	ASTM D5185m		<1	0	0
Calcium	ppm	ASTM D5185m		3	0	0
Phosphorus	ppm	ASTM D5185m		1248	5	2
Zinc	ppm	ASTM D5185m		13	7	0
Sulfur	ppm	ASTM D5185m		20	50	38
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	7	36	30
Sodium	ppm	ASTM D5185m		0	<1	0
Potassium	ppm	ASTM D5185m	>20	0	0	<1
		AOTAL DOGGA	>0.02	△ 0.030	0.023	0.009
Water	%	ASTM D6304	<i>></i> 0.02	0.030	0.020	0.000
Water ppm Water	% ppm	ASTM D6304 ASTM D6304	>250	▲ 302	239.8	97.7
	ppm					



OIL ANALYSIS REPORT









VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.02	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERTIES		method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445		40.8	46.7	43.4
SAMPLE IMAGES		method	limit/base	current	history1	history2


GRAPHS


Color

Bottom













Certificate 12367

Laboratory Sample No.

Lab Number : 06147401

: WC0812072

Unique Number : 10977479 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 12 Apr 2024

Tested : 15 Apr 2024 Diagnosed

: 16 Apr 2024 - Don Baldridge

US 23228 Contact: AMANDA CARRIER

amanda.carrier@daikinapplied.com T: (804)747-4822

DAIKIN APPLIED-RICHMOND

8991 OLD STAPLES MILL ROAD

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (804)747-6686

HENRICO, VA