


OIL ANALYSIS REPORT

S46 [284565] **PNEUTECH AK100017020 - AVA**

Component Compressor



Recommendation

Resample at the next service interval to monitor.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UFD0001592		
Sample Date		Client Info		02 Apr 2024		
Machine Age	hrs	Client Info		852		
Oil Age	hrs	Client Info		1		
Oil Changed		Client Info		Not Changd		
Sample Status				NORMAL		
CONTAMINATION	V	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	<1		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m		<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	2		
Lead	ppm	ASTM D5185m	>25	<1		
Copper	ppm	ASTM D5185m	>50	1		
Tin	ppm	ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		2		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		1		
Phosphorus	ppm	ASTM D5185m		416		
Zinc	ppm	ASTM D5185m		7		
Sulfur	ppm	ASTM D5185m		1369		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	6		
Sodium	ppm	ASTM D5185m		1		
Potassium	ppm	ASTM D5185m	>20	3		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.51		



OIL ANALYSIS REPORT







Color	国政	no image	no image
Bottom		no image	no image
GRAPHS			



	Non-ferrous Metals	
	copper	
_	energenena tin	
mdd		
	÷	44
	2/2	vpr2/24
	Api	Api
	Apr2/24	Anr2/









Laboratory Sample No.

Lab Number : 06156128 Unique Number : 10991551

: UFD0001592

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 22 Apr 2024 **Tested** : 23 Apr 2024

Diagnosed

: 24 Apr 2024 - Sean Felton

Test Package : IND 2 Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: UCFLUBUR [WUSCAR] 06156128 (Generated: 04/24/2024 13:57:19) Rev: 1

Contact/Location: Service Manager - UCFLUBUR

FLUID-AIRE DYNAMICS - (MN)

14250 JUDICIAL ROAD

Contact: Service Manager

BURNSVILLE, MN

US 55306

T:

F: