

PROBLEM SUMMARY

Sample Rating Trend




Machine Id

BOPPER - QUALITY EP 150

Gearbox

{not provided} (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE					
Iron	ppm	ASTM D5185m	>200	883					
Copper	ppm	ASTM D5185m	>200	4 397					
Tin	ppm	ASTM D5185m	>25	^ 25					

Customer Id: QUAROC Sample No.: WC06157820 Lab Number: 06157820 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.				
Change Fluid			?	We recommend that you drain the oil from the component if this has not already been done.				
Resample			?	We recommend an early resample to monitor this condition.				

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

BOPPER - QUALITY EP 150

Component **Gearbox**

{not provided} (--- GAL)

DIAGNOSIS

Recommendation

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

Wear

The iron level is severe. Gear wear is indicated. Bearing and/or bushing wear is indicated.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The oil is no longer serviceable as a result of the abnormal and/or severe wear.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC06157820		
Sample Date		Client Info		22 Apr 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	883		
Chromium	ppm	ASTM D5185m	>15	3		
Nickel	ppm	ASTM D5185m	>15	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	10		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>200	4 397		
Tin	ppm	ASTM D5185m	>25	<u>^</u> 25		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		2		
Barium	ppm	ASTM D5185m		2		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		3		
Magnesium	ppm	ASTM D5185m		2		
Calcium	ppm	ASTM D5185m		13		
Phosphorus	ppm	ASTM D5185m		328		
Zinc	ppm	ASTM D5185m		63		
Sulfur	ppm	ASTM D5185m		4777		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	16		
Sodium	ppm	ASTM D5185m		11		
Potassium	ppm	ASTM D5185m	>20	2		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		2.09		



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: WC06157820 Lab Number : 06157820 Unique Number : 10993243

Test Package : IND 2

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 23 Apr 2024 Tested : 24 Apr 2024

Diagnosed : 25 Apr 2024 - Don Baldridge

US 28379 Contact: JASON STROLL jstroll@qualityoilandgas.com T: (910)997-3101

203 WEST BROAD AVE

ROCKINGHAM, NC

QUALITY OIL AND GAS COMPANY

 st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: QUAROC [WUSCAR] 06157820 (Generated: 04/25/2024 13:28:46) Rev: 1

Contact/Location: JASON STROLL - QUAROC

F: x: