







**FUEL REPORT**

**GRAPHS**



**Laboratory** : WearCheck USA - 501 Madison Ave., Cary, NC 27513  
**Sample No.** : VCP395169      **Received** : 24 Apr 2024  
**Lab Number** : **06159555**      **Tested** : 26 Apr 2024  
**Unique Number** : 10994978      **Diagnosed** : 26 Apr 2024 - Jonathan Hester  
**Test Package** : MOB 1 ( Additional Tests: KF )

**ALTA EQUIPMENT**  
 420 NOLEN DRIVE  
 SOUTH ELGIN, IL  
 US 60177  
 Contact: CHRIS WILSON  
 chris.wilson@altg.com  
 T: (815)441-4623  
 F:

To discuss this sample report, contact Customer Service at 1-800-237-1369.  
 \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.  
 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)