


OIL ANALYSIS REPORT

ECORE LANCASTER EQ MIXER PRESS - ECORE LANCASTER

Hydraulic System

SHELL TELLUS S2 MX 68 (--- GAL)



DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

The copper level is abnormal. All other component wear rates are normal.

Contamination

There is a high amount of silt (particulates < 6 microns in size) present in the oil.

Fluid Condition

The oil viscosity is lower than normal. Confirm oil type. The AN level is acceptable for this fluid.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0892736		
Sample Date		Client Info		24 May 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.05	NEG		
WEAR METALS		method	limit/base	current	history1	history2
ron	ppm	ASTM D5185m	>20	<1		
Chromium	ppm	ASTM D5185m	>20	<1		
Nickel	ppm	ASTM D5185m	>20	<1		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>20	2		
_ead	ppm	ASTM D5185m	>20	3		
Copper	ppm	ASTM D5185m	>20	<u></u> 37		
Γin	ppm	ASTM D5185m	>20	3		
/anadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		<1		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		<1		
Molybdenum	ppm	ASTM D5185m		<1		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		6		
Calcium	ppm	ASTM D5185m		52		
Phosphorus	ppm	ASTM D5185m		277		
Zinc	ppm	ASTM D5185m		284		
Sulfur	ppm	ASTM D5185m		3867		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	<1		
Sodium	ppm	ASTM D5185m		4		
Potassium	ppm	ASTM D5185m	>20	2		
FLUID CLEANLIN	NESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>5000	<u></u> 4 30548		
Particles >6µm		ASTM D7647	>1300	987		
Particles >14µm		ASTM D7647	>160	9		
Particles >21μm		ASTM D7647	>40	2		
Particles >38µm		ASTM D7647	>10	0		
Particles >71μm		ASTM D7647	>3	0		
Oil Cleanliness		ISO 4406 (c)	>19/17/14	<u>22/17/10</u>		


Acid Number (AN)

mg KOH/g ASTM D8045

Contact/Location: Bill Trimmer - MOTYOR



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: WC0892736 Lab Number : 06195394 Unique Number : 11057517 Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 30 May 2024 **Tested** : 04 Jun 2024

Diagnosed : 05 Jun 2024 - Jonathan Hester

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

MOTOR TECHNOLOGY INC

515 WILLOW SPRINGS LN YORK, PA

US 17406 Contact: Bill Trimmer

btrimmer@motortechnologyinc.com T: (717)266-4045