


OIL ANALYSIS REPORT

ECORE LANCASTER EQ MIXER INCLINE CONVEYOR - ECORE LANCASTER

Gearbox

MOBIL OMALA S4 GXV 220 (--- GAL)



DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Resample at the next service interval to monitor.

Gear wear is indicated. All other component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	ATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0929576		
Sample Date		Client Info		24 May 2024		
Machine Age	yrs	Client Info		0		
Oil Age	yrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
CONTAMINATION		method	limit/base	current	history1	history2
Water		WC Method	>0.2	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	4 347		
Chromium	ppm	ASTM D5185m	>15	2		
Nickel	ppm	ASTM D5185m	>15	0		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	3		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>200	<1		
Tin	ppm	ASTM D5185m	>25	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		16		
Barium	ppm	ASTM D5185m		<1		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		6		
Magnesium	ppm	ASTM D5185m		3		
Calcium	ppm	ASTM D5185m		37		
Phosphorus	ppm	ASTM D5185m		417		
Zinc	ppm	ASTM D5185m		29		
Sulfur	ppm	ASTM D5185m		6470		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	16		
Sodium	ppm	ASTM D5185m		1		
Potassium	ppm	ASTM D5185m	>20	<1		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2


0.70

Acid Number (AN)

mg KOH/g ASTM D8045



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: WC0929576 Lab Number : 06195592 Unique Number : 11057715

Test Package : IND 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 30 May 2024 **Tested** : 05 Jun 2024

Diagnosed

: 05 Jun 2024 - Don Baldridge

To discuss this sample report, contact Customer Service at 1-800-237-1369.

Contact: Bill Trimmer btrimmer@motortechnologyinc.com T: (717)266-4045

MOTOR TECHNOLOGY INC

515 WILLOW SPRINGS LN

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: Bill Trimmer - MOTYOR

YORK, PA

US 17406