


OIL ANALYSIS REPORT

Batch Line

Vacuum Pump Mixer A (S/N 0614167962)

Vacuum Pump

{not provided} (--- GAL)



DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition.

Wear

All component wear rates are normal.

Contamination

Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. There is a moderate amount of visible silt present in the sample.


Fluid Condition

The AN level is acceptable for this fluid. The oil is no longer serviceable due to the presence of contaminants.

SAMPLE INFORM	MOITAN	method	limit/base	current	history1	history2
Sample Number		Client Info		HPL0004274		
Sample Date		Client Info		22 May 2024		
Machine Age	hrs	Client Info		27		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>.1	NEG		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	8		
Chromium	ppm	ASTM D5185m	>20	0		
Nickel	ppm	ASTM D5185m	>20	0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>20	52		
Lead	ppm	ASTM D5185m	>20	0		
Copper	ppm	ASTM D5185m	>20	0		
Tin	ppm	ASTM D5185m	>20	2		
Vanadium	ppm	ASTM D5185m		<1		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		10		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m		1		
Calcium	ppm	ASTM D5185m		1		
Phosphorus	ppm	ASTM D5185m		27		
Zinc	ppm	ASTM D5185m		9		
Sulfur	ppm	ASTM D5185m		760		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	4 547		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	<1		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
I EOID DEGITION					,	



OIL ANALYSIS REPORT





Certificate 12367

Laboratory Sample No.

: HPL0004274 Lab Number : 06195994 Unique Number : 11058117 Test Package : MOB 2

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 30 May 2024 : 04 Jun 2024 Tested

Diagnosed : 04 Jun 2024 - Jonathan Hester

248 JOHNSON RILEY ROAD CALVERT CITY, KY US 42029

Contact: MICHAEL WARD michael.ward@sekisui-pmt-us.com

SEKISUI POLYMATECH AMERICA LLC

To discuss this sample report, contact Customer Service at 1-800-237-1369. st - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F:

Report Id: SEKCAL [WUSCAR] 06195994 (Generated: 06/04/2024 17:00:03) Rev: 1

Contact/Location: MICHAEL WARD - SEKCAL

T: