

COOLANT REPORT

Sample Rating Trend





1469
Component
Coolant
Fluid
{not provided} (--- GAL)

	~ •	10	\sim	\sim
 ΙΔ	G١	u n	9	S

Machine Id

Recommendation

We recommend drain/flush system, and refill with 50/50 antifreeze water mixture. Please note that the coolant was too contaminated to perform the normal laboratory tests. (Customer Sample Comment: Obvious contamination)

Contaminants

There is a high concentration of oil present in the coolant.


Coolant Condition

The coolant is no longer serviceable due to the presence of contaminants.

				Jan 2024		
				PSUSIBLE		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0847914		
Sample Date		Client Info		29 Jan 2024		
Machine Age	hrs	Client Info		10965		
Oil Age	hrs	Client Info		10965		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
VISUAL		method	limit/base	current	history1	history2
Color					no image	no image
Bottom					no image	no image



COOLANT REPORT







Laboratory: WearCheck USA - 501 Madison Ave., Cary, NC 27513 **Sample No.** : WC0847914 **Lab Number** : 06199746

Unique Number : 11061869

Received : 04 Jun 2024 Tested : 17 Jun 2024

Diagnosed : 17 Jun 2024 - Doug Bogart

Apple Valley Waste - Chambersburg Location 5436 Sunset Pike Chambersburg, PA US 17202

Contact: Service Manager

Test Package : COOL- (Additional Tests: BoilingPoint, COOL, SCREEN) Certificate 12367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: