


PROBLEM SUMMARY


Sample Rating Trend




DAC-2
Component
Gearbox

ROYAL PURPLE SYNFILM GT 68 (--- GAL)

COMPONENT CONDITION SUMMARY





RECOMMENDATION

We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE	ABNORMAL	ABNORMAL			
Iron	ppm	ASTM D5185m	>200	474	<u></u> 146	<1			
Copper	nnm	ASTM D5185m	>200	435	A 138	2			

Customer Id: ENGBOS Sample No.: RP0043315 Lab Number: 06200262 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.		
Resample			?	We recommend an early resample to monitor this condition.		

HISTORICAL DIAGNOSIS

13 Mar 2024 Diag: Jonathan Hester

WEAR



No corrective action is recommended at this time. We recommend an early resample to monitor this condition. Bearing and/or gear wear is indicated. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



VIS DEBRIS



10 Dec 2023 Diag: Don Baldridge
We recommend you service the filters on this component if applicable. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





10 Sep 2023 Diag: Wes Davis




Resample at the next service interval to monitor. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.All component wear rates are normal. The water content is negligible. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend





DAC-2
Component
Gearbox
Fluid
ROYAL PURPLE SYNFILM GT 68 (--- GAL)

DIAGNOSIS

Machine Id

Recommendation

We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

Wear

Gear wear is indicated. Bearing and/or bushing wear is indicated.

Contamination

There is no indication of any contamination in the

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		RP0043315	RP0039484	RP0038811
Sample Date		Client Info		04 Jun 2024	13 Mar 2024	10 Dec 2023
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	474	<u> </u>	<1
Chromium	ppm	ASTM D5185m	>15	4	3	0
Nickel	ppm	ASTM D5185m	>15	0	0	0
Titanium	ppm	ASTM D5185m		0	<1	0
Silver	ppm	ASTM D5185m		12	<1	0
Aluminum	ppm	ASTM D5185m	>25	2	1	<1
Lead	ppm	ASTM D5185m	>100	8	6	0
Copper	ppm	ASTM D5185m	>200	435	△ 138	2
Tin	ppm	ASTM D5185m	>25	0	<1	0
Vanadium	ppm	ASTM D5185m		0	<1	0
Cadmium	ppm	ASTM D5185m		4	1	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	0	0
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		3	2	0
Magnesium	ppm	ASTM D5185m	90	41	44	83
Calcium	ppm	ASTM D5185m		71	<1	2
Phosphorus	ppm	ASTM D5185m		9	5	4
Zinc	ppm	ASTM D5185m		65	18	0
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>50	18	4	<1
Sodium	ppm	ASTM D5185m		2	3	0
Potassium	ppm	ASTM D5185m	>20	0	2	1
Water	%	ASTM D6304	>0.2	0.018	0.028	0.024
ppm Water	ppm	ASTM D6304	>2000	181	284	244
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		0.39	0.48	0.41
VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	NONE	▲ MODER
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.2	NEG	NEG	NEG


TERTISE SAUVEUR NEW GBOS

NEG

scalar *Visual



OIL ANALYSIS REPORT







Certificate 12367

Laboratory

Sample No. : RP0043315 Lab Number : 06200262 Unique Number : 11062385

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 05 Jun 2024 **Tested** : 06 Jun 2024

Diagnosed : 07 Jun 2024 - Don Baldridge

Test Package : IND 2 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

BOSTON, MA US 02215 Contact: ROBERT ST SAUVEUR

474 BROOKLINE AVE

robert.stsauveur@engie.com T: (401)651-9381