

## **PROBLEM SUMMARY**

Sample Rating Trend



#### Machine Id Forward drive roll Component Gearbox Fluid MOBIL MOBILGEAR SHC 320 (--- GAL)

### COMPONENT CONDITION SUMMARY



#### RECOMMENDATION

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

### PROBLEMATIC TEST RESULTS

Sample Status			SEVERE	 
Particles >4µm	ASTM D7647	>20000	<b>A</b> 228832	 
Particles >6µm	ASTM D7647	>5000	<b>194482</b>	 
Particles >14µm	ASTM D7647	>640	<b>4</b> 53652	 
Particles >21µm	ASTM D7647	>160	<b>4</b> 5971	 
Oil Cleanliness	ISO 4406 (c)	>21/19/16	<b>a</b> 25/25/23	 

Customer Id: CASASH Sample No.: WC0776528 Lab Number: 06204634 Test Package: PLANT



To manage this report scan the QR code

To discuss the diagnosis or test data: Wes Davis +1 905-569-8600 x223 wesd@wearcheck.ca

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS								
Action	Status	Date	Done By	Description				
Change Filter			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				
Resample			?	Resample in 30-45 days to monitor this situation.				
Information Required			?	NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.				
Check Breathers			?	The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather.				
Check Dirt Access			?	We advise that you check all areas where contaminants can enter the system.				
Filter Fluid			?	We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid.				

## HISTORICAL DIAGNOSIS



## **OIL ANALYSIS REPORT**



#### Machine Id Forward drive roll Component Gearbox Fluid MOBIL MOBILGEAR SHC 320 (--- GAL)

#### DIAGNOSIS

#### Recommendation

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. NOTE: Please provide information regarding reservoir capacity, filter type and micron rating with next sample.

#### Wear

All component wear rates are normal.

#### Contamination

There is a high amount of particulates (2 to 100 microns in size) present in the oil. The water content is negligible.

#### Fluid Condition

The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

SAMPLE INFORM	<b>IATION</b>	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0776528		
Sample Date		Client Info		06 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>200	34		
Chromium	ppm	ASTM D5185m	>15	0		
Nickel	ppm	ASTM D5185m	>15	<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	0		
Lead	ppm	ASTM D5185m	>100	0		
Copper	ppm	ASTM D5185m	>200	50		
Tin	ppm	ASTM D5185m	>25	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES	pp	method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	IIIIII/Dase	<1	history1	TIIStor yz
Barium	ppm ppm	ASTM D5185m		<1		
Molybdenum		ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		<1		
Calcium	ppm	ASTM D5185m		<1		
	ppm	ASTM D5185m		304		
Phosphorus	ppm			11		
Zinc Sulfur	ppm	ASTM D5185m				
	ppm	ASTM D5185m		3642		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm		>50	19		
Sodium	ppm	ASTM D5185m		<1		
Potassium	ppm	ASTM D5185m	>20	3		
Water	%	ASTM D6304		0.010		
ppm Water	ppm	ASTM D6304	>2000	106		
FLUID CLEANLIN	IESS	method	limit/base	current	history1	history2
Particles >4µm		ASTM D7647	>20000	<b>A</b> 228832		
Particles >6µm		ASTM D7647	>5000	<b>4</b> 194482		
Particles >14µm		ASTM D7647	>640	<b>53652</b>		
Particles >21µm		ASTM D7647	>160	<b>4</b> 5971		
Particles >38µm		ASTM D7647	>40	3		
Particles >71µm		ASTM D7647	>10	0		
Oil Cleanliness		ISO 4406 (c)	>21/19/16	<b>2</b> 5/25/23		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045		1.33		



Water

Water (

# **OIL ANALYSIS REPORT**

NONE

NONE

NONE

NONE

NONE

NONE

NORML

NORML

NEG

NEG

309

Particle Count

Acid Number

491.5

122,880

30.72

7.68

480

120

31

(mg KOH/g)

nuper 0.5

Acid P

un6/24

Jun6/24 -

per 1 1.920 no image


no image

no image

no imade

4406

:1999 Cle



CASCADES CONTAINERBOARD PACKAGING - BEARPACK PROJECT 10026 OLD RIDGE ROAD ASHLAND, VA US 23005 Contact: MARC-ANDRE HUBERT marc-andre\_hubert@cascades.com T: F:

214

38L

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: CASASH [WUSCAR] 06204634 (Generated: 06/11/2024 19:43:05) Rev: 1

Submitted By: MARC-ANDRE HUBERT

Page 4 of 4