


OIL ANALYSIS REPORT

Sample Rating Trend



NORMAL



Machine Id
311
Component
Compressor
Fluid
VILTER ISO 150 (--- GAL)

DIAGNOSIS

Recommendation

Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is no indication of any contamination in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0881064	WC0881068	WC0843784
Sample Date		Client Info		03 Jun 2024	26 Apr 2024	27 Mar 2024
Machine Age	hrs	Client Info		4661	3888	3566
Oil Age	hrs	Client Info		4661	3888	0
Oil Changed		Client Info		Not Changd	Not Changd	Not Changd
Sample Status				NORMAL	NORMAL	NORMAL
CONTAMINATION	١	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	3	3	3
Chromium	ppm	ASTM D5185m	>5	0	<1	0
Nickel	ppm	ASTM D5185m		0	<1	0
Titanium	ppm	ASTM D5185m		<1	<1	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>15	0	2	0
Lead	ppm	ASTM D5185m	>65	<1	<1	0
Copper	ppm	ASTM D5185m	>65	1	1	<1
Tin	ppm	ASTM D5185m	>10	0	<1	0
Vanadium	ppm	ASTM D5185m		<1	<1	0
Cadmium	ppm	ASTM D5185m		0	<1	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m		0	3	7
Molybdenum	ppm	ASTM D5185m		0	<1	0
Manganese	ppm	ASTM D5185m		<1	<1	0
Magnesium	ppm	ASTM D5185m		0	<1	0
Calcium	ppm	ASTM D5185m		4	13	11
Phosphorus	ppm	ASTM D5185m		15	20	20
Zinc	ppm	ASTM D5185m		4	6	4
Sulfur	ppm	ASTM D5185m		20	0	77
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>35	2	<1	<1
Sodium	ppm	ASTM D5185m		2	1	<1
		ASTM D5185m	>20	2	2	0
Potassium	ppm	ASTIVI DSTOSIII	720	2	_	U
Potassium FLUID DEGRADA	• •	method	limit/base	current	history1	history2



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: WC0881064 Lab Number : 06204857 Unique Number : 11072318

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 10 Jun 2024

Tested : 12 Jun 2024 Diagnosed

: 12 Jun 2024 - Sean Felton

31725 ROUTE 83 GRAYSLAKE, IL US 60030 Contact: ERIC BOEHMER eboehmer@esisolutions.com

TERREVA RENEWABLES - COUNTRYSIDE

Test Package : MOB 2 (Additional Tests: TBN) To discuss this sample report, contact Customer Service at 1-800-237-1369. * - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Report Id: TERGRAIL [WUSCAR] 06204857 (Generated: 06/12/2024 18:50:38) Rev: 1

Contact/Location: ERIC BOEHMER - TERGRAIL

T:

F: