


PROBLEM SUMMARY

Sample Rating Trend



AURORA PO-5060 QUINCY BU0908140053 - PEPSI

Component Compressor



RECOMMENDATION

We advise that you check for a possible overheat condition. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status				SEVERE	ABNORMAL	NORMAL		
Acid Number (AN)	mg KOH/g	ASTM D8045	0.337	11.7	△ 2.89	0.993		

Customer Id: UCPATRAL Sample No.: UCP06208813 Lab Number: 06208813 Test Package: IND 2 To manage this report scan the QR code To discuss the diagnosis or test data: Don Baldridge +1 don.b505@comcast.net To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Change Fluid			?	Oil and filter change at the time of sampling has been noted.		
Change Filter			?	Oil and filter change at the time of sampling has been noted.		
Resample			?	We recommend an early resample to monitor this condition.		
Check For Overheating			?	We advise that you check for a possible overheat condition.		

HISTORICAL DIAGNOSIS

20 Nov 2023 Diag: Jonathan Hester

DEGRADATION



We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is above the recommended limit.



NORMAL



11 Jun 2021 Diag: Angela Borella

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



NORMAL



23 Jan 2020 Diag: Don Baldridge

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.






OIL ANALYSIS REPORT

AURORA PO-5060 **QUINCY BU0908140053 - PEPSI**

Compressor



DIAGNOSIS

Recommendation

We advise that you check for a possible overheat condition. Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

All component wear rates are normal.

Contamination

There is no indication of any contamination in the


Fluid Condition

The AN level is above the recommended limit. The oil viscosity is higher than normal. TAN level indicates possible presence of varnish.


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCP06208813	UCP06015247	UCP05291347
Sample Date		Client Info		08 May 2024	20 Nov 2023	11 Jun 2021
Machine Age	hrs	Client Info		87253	83178	62002
Oil Age	hrs	Client Info		10000	6000	4102
Oil Changed		Client Info		Changed	Not Changd	Changed
Sample Status				SEVERE	ABNORMAL	NORMAL
CONTAMINATION	N	method	limit/base	current	history1	history2
Water		WC Method	>0.1	NEG	NEG	NEG
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	0	5	<1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m		0	0	<1
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>25	0	0	0
Lead	ppm	ASTM D5185m	>25	0	0	0
Copper	ppm	ASTM D5185m	>50	10	5	2
Tin	ppm	ASTM D5185m	>15	<1	0	0
Antimony	ppm	ASTM D5185m				<1
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		0	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	1	<1	0	0
Barium	ppm	ASTM D5185m	0.3	0	0	0
Molybdenum	ppm	ASTM D5185m	0	0	0	0
Manganese	ppm	ASTM D5185m	0	0	<1	0
Magnesium	ppm	ASTM D5185m	0	0	0	0
Calcium	ppm	ASTM D5185m	0.5	0	0	0
Phosphorus	ppm	ASTM D5185m	536	134	167	230
Zinc	ppm	ASTM D5185m	0.2	0	2	8
Sulfur	ppm	ASTM D5185m	649	81	239	244
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	1	1	3
Sodium	ppm	ASTM D5185m		4	<1	9
Potassium	ppm	ASTM D5185m	>20	<1	0	1
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.337	▲ 11.7	2.89	0.993



OIL ANALYSIS REPORT



VISUAL		method	limit/base	current	history1	history2
White Metal	scalar	*Visual	NONE	NONE	LIGHT	VLITE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT	NONE
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.1	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	TES	method	limit/base	current	history1	history2
Visc @ 40°C	cSt	ASTM D445	42.0	74.7	46.4	45.1
SAMPLE IMAGES	6	method	limit/base	current	history1	history2
Color						
Bottom						







Certificate 12367

Laboratory Sample No.

Lab Number : 06208813 Unique Number : 11076274

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : UCP06208813

Test Package : IND 2

Received : 13 Jun 2024 : 14 Jun 2024 **Tested**

Diagnosed

To discuss this sample report, contact Customer Service at 1-800-237-1369.

: 17 Jun 2024 - Don Baldridge

US 27616 Contact: AARON MCCOY

aaron.mccoy@pattonsinc.com T: (919)872-6411

PATTONS INC - RALEIGH

2616 DISCOVERY DRIVE

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)876-1961 Contact/Location: AARON MCCOY - UCPATRAL

RALEIGH, NC