

PROBLEM SUMMARY

1

Sample Rating Trend

WATER

WATER

NOT GIVEN Machine Id SULLAIR 5559893 - GKN AEROSPACE Component Compressor

COMPONENT CONDITION SUMMARY

No relevant graphs to display

RECOMMENDATION

Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS								
Sample Status			SEVERE					
Free Water	scalar	*Visual	▲ >10%					

Customer Id: UCAIRCAR Sample No.: UCH06215863 Lab Number: 06215863 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data: Don Baldridge +1

don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action Change Fluid	Status	Date	Done By	Description Oil and filter change at the time of sampling has been noted.			
Change Filter			?	Oil and filter change at the time of sampling has been noted.			
Resample			?	We recommend an early resample to monitor this condition.			


HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

NOT GIVEN **SULLAIR 5559893 - GKN AEROSPACE**

Component Compressor



DIAGNOSIS

▲ Recommendation

Oil and filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.

All component wear rates are normal.

Contamination

Excessive free water present.

Fluid Condition

The AN level is acceptable for this fluid.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		UCH06215863		
Sample Date		Client Info		14 Jun 2024		
Machine Age	hrs	Client Info		16100		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		Changed		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	4		
Chromium	ppm	ASTM D5185m	>10	0		
Nickel	ppm	ASTM D5185m		<1		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	<1		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	0		
Tin	ppm	ASTM D5185m	>15	<1		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		0		
Barium	ppm	ASTM D5185m		0		
Molybdenum	ppm	ASTM D5185m		0		
Manganese	ppm	ASTM D5185m		<1		
Magnesium	ppm	ASTM D5185m		0		
Calcium	ppm	ASTM D5185m		0		
Phosphorus	ppm	ASTM D5185m		256		
Zinc	ppm	ASTM D5185m		5		
Sulfur	ppm	ASTM D5185m		0		
CONTAMINANTS		method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	<1		
Sodium	ppm	ASTM D5185m		2		
Potassium	ppm	ASTM D5185m	>20	3		
Water	%	ASTM D6304	>0.1	0.097		
ppm Water	ppm	ASTM D6304	>1000	970		
FLUID DEGRADA	TION	method	limit/base	current	history1	history2


0.24

Acid Number (AN)

mg KOH/g ASTM D8045



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : UCH06215863 Lab Number : 06215863

Received Unique Number : 11088727

Tested : 21 Jun 2024 Diagnosed : 22 Jun 2024 - Don Baldridge

: 20 Jun 2024

Test Package : IND 2 (Additional Tests: KF) To discuss this sample report, contact Customer Service at 1-800-237-1369.

Contact: ELVIN DIAZ ediaz@airmaticcompressor.com;canastasio@wearcheckusa.com T: (800)864-7621

 st - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: ELVIN DIAZ - UCAIRCAR

AIRMATIC COMPRESSOR SYSTEMS

700 WASHINGTON AVE

CARLSTADT, NJ

F: (201)342-6241

US 07072

Report Id: UCAIRCAR [WUSCAR] 06215863 (Generated: 06/23/2024 06:03:07) Rev: 1