

PROBLEM SUMMARY

Sample Rating Trend

WATER


Machine Id


NK 112123 (S/N SC356036)

Compressor

CIMARRON HB-150 (--- GAL)







RECOMMENDATION

We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. There is too much water present in this sample to perform a particle count.

PROBLEMATIC TEST RESULTS									
Sample Status				SEVERE					
Iron	ppm	ASTM D5185m	>50	122					
Water	%	ASTM D6304	>2.26	8.90					
ppm Water	ppm	ASTM D6304	>22600	89000					

Customer Id: CIMCAR Sample No.: TO90004140 Lab Number: 06221294 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com


RECOMMENDED ACTIONS						
Action	Status	Date	Done By	Description		
Water Drain-off			?	We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid.		
Resample			?	We recommend an early resample to monitor this condition.		

HISTORICAL DIAGNOSIS



OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

NK 112123 (S/N SC356036)

Compressor

CIMARRON HB-150 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you follow the water drain-off procedure for this component, and use off-line filtration to improve the cleanliness of the system fluid. We recommend an early resample to monitor this condition. There is too much water present in this sample to perform a particle count.

Wear

The iron level is abnormal.

Contamination

There is a high concentration of water present in the oil.

Fluid Condition

The AN level is acceptable for this fluid.

		<u></u>		Jun 2024		
SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		TO90004140		
Sample Date		Client Info		13 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				SEVERE		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>50	122		
Chromium	ppm	ASTM D5185m	>10	<1		
Nickel	ppm	ASTM D5185m		0		
Titanium	ppm	ASTM D5185m		0		
Silver	ppm	ASTM D5185m		0		
Aluminum	ppm	ASTM D5185m	>25	6		
Lead	ppm	ASTM D5185m	>25	0		
Copper	ppm	ASTM D5185m	>50	0		
Tin	ppm	ASTM D5185m	>15	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	0	3		
Barium	ppm	ASTM D5185m	0	0		
Molybdenum	ppm	ASTM D5185m	0	0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m	0	2		
Calcium	ppm	ASTM D5185m	0	21		
Phosphorus	ppm	ASTM D5185m	0	38		
Zinc	ppm	ASTM D5185m	0	29		
Sulfur	ppm	ASTM D5185m	0	2477		
CONTAMINANTS	;	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>25	1		
Sodium	ppm	ASTM D5185m		12		
Potassium	ppm	ASTM D5185m	>20	10		
Water	%	ASTM D6304	>2.26	8.90		
ppm Water	ppm	ASTM D6304	>22600	89000		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2


1.23

Acid Number (AN)

mg KOH/g ASTM D8045



OIL ANALYSIS REPORT





Certificate 12367

Laboratory Sample No.

: TO90004140 Lab Number : 06221294 Unique Number : 11099491

Received : 26 Jun 2024 **Tested** : 27 Jun 2024

: 27 Jun 2024 - Don Baldridge Diagnosed

Test Package : IND 2 (Additional Tests: KF, KV100, PrtCount, VI) To discuss this sample report, contact Customer Service at 1-800-237-1369. st - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

UM 88220-8923 Contact: CARLOS LEAL

cleal@cimarron.com T:

4425 GRANDI RD, UNIT F

CARLSBAD, NM

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: