


OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

NOT GIVEN WC06221309 (S/N NO INFO ON SIF/BOTTLE)

Refrigeration Compressor

REFRIG COMP OIL ISO 46 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. We recommend an early resample to monitor this condition.

Wear

The iron level is abnormal. The chromium level is abnormal.

Contamination

There is a light concentration of water present in the

Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC06221309		
Sample Date		Client Info		25 Jun 2024		
Machine Age	hrs	Client Info		0		
Oil Age	hrs	Client Info		0		
Oil Changed		Client Info		N/A		
Sample Status				ABNORMAL		
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>8	<u> </u>		
Chromium	ppm	ASTM D5185m	>2	<u></u> 3		
Nickel	ppm	ASTM D5185m		5		
Titanium	ppm	ASTM D5185m		<1		
Silver	ppm	ASTM D5185m	>2	0		
Aluminum	ppm	ASTM D5185m	>3	2		
Lead	ppm	ASTM D5185m	>2	0		
Copper	ppm	ASTM D5185m	>8	<1		
Tin	ppm	ASTM D5185m	>4	0		
Vanadium	ppm	ASTM D5185m		0		
Cadmium	ppm	ASTM D5185m		0		
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m	5	0		
Barium	ppm	ASTM D5185m	5	0		
Molybdenum	ppm	ASTM D5185m	5	0		
Manganese	ppm	ASTM D5185m		0		
Magnesium	ppm	ASTM D5185m	5	<1		
Calcium	ppm	ASTM D5185m	12	0		
Phosphorus	ppm	ASTM D5185m	12	0		
Zinc	ppm	ASTM D5185m	12	0		
Sulfur	ppm	ASTM D5185m	1000	0		
CONTAMINANTS	3	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	8		
Sodium	ppm	ASTM D5185m		0		
Potassium	ppm	ASTM D5185m	>20	1		
Water	%	ASTM D6304	>0.01	△ 0.093		
ppm Water	ppm	ASTM D6304	>100	<u> </u>		
FLUID DEGRADA	ATION	method	limit/base	current	history1	history2
	140111		0.40	0.04:		


Acid Number (AN)

mg KOH/g ASTM D974 0.10

0.014



OIL ANALYSIS REPORT







Certificate 12367

Report Id: MCQUPP [WUSCAR] 06221309 (Generated: 06/28/2024 10:57:06) Rev: 1

Laboratory Sample No.

Lab Number : 06221309

Test Package : IND 2

: WC06221309 Unique Number : 11099506

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 26 Jun 2024 **Tested** : 27 Jun 2024 Diagnosed

: 28 Jun 2024 - Jonathan Hester

DAIKIN APPLIED 5021 HOWERTON WAY SUITE P BOWIE, MD US 20715

Contact: ANDREW TURLINGTON andrew.turlington@daikinapplied.com T: (301)735-1440

To discuss this sample report, contact Customer Service at 1-800-237-1369. st - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (301)735-1838