


PROBLEM SUMMARY

Sample Rating Trend




Machine Id


PRESS 1 (S/N 420-235)


Northwest Roller Bearing

ROYAL PURPLE THERMYL-GLYDE 1500 (--- GAL)

COMPONENT CONDITION SUMMARY







RECOMMENDATION

We advise that you check all areas where dirt can enter the system. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

PROBLEMATIC TEST RESULTS							
Sample Status				SEVERE	SEVERE	SEVERE	
Iron	ppm	ASTM D5185m	>20	334	1 240	▲ 163	
Chromium	ppm	ASTM D5185m	>20	▲ 65	11	8	
Nickel	ppm	ASTM D5185m	>20	201	4 0	<u>^</u> 32	
Silicon	ppm	ASTM D5185m	>15	292	△ 32	<u>^</u> 29	

Customer Id: WEYNEW Sample No.: WC0892348 Lab Number: 06236098 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED A	RECOMMENDED ACTIONS					
Action	Status	Date	Done By	Description		
Inspect Wear Source			?	We advise that you inspect for the source(s) of wear.		
Resample			?	We recommend an early resample to monitor this condition.		
Check Dirt Access			?	We advise that you check all areas where dirt can enter the system.		

HISTORICAL DIAGNOSIS

25 Mar 2024 Diag: Jonathan Hester

WEAR



We advise that you check all areas where dirt can enter the system. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. The iron level is severe. The nickel level is abnormal. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The water content is negligible. The AN level is acceptable for this fluid.



WEAR



11 Jan 2024 Diag: Jonathan Hester

We advise that you check all areas where dirt can enter the system. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. The iron level is severe. The nickel level is abnormal. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The water content is negligible. The AN level is acceptable for this fluid.



NORMAL



01 Aug 2023 Diag: Don Baldridge


Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT

Sample Rating Trend



Machine Id

PRESS 1 (S/N 420-235)

Northwest Roller Bearing

ROYAL PURPLE THERMYL-GLYDE 1500 (--- GAL)

DIAGNOSIS

Recommendation

We advise that you check all areas where dirt can enter the system. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.

The iron, chrome and nickel levels are severe. Gear wear is indicated.

Contamination

Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The water content is negligible.

Fluid Condition

The AN level is acceptable for this fluid.

J 1_/						
SAMPLE INFOR	MATION	method	limit/base	current	history1	history2
Sample Number		Client Info		WC0892348	WC0432397	RP0008383
Sample Date		Client Info		03 Jul 2024	25 Mar 2024	11 Jan 2024
Machine Age	hrs	Client Info		0	0	0
Oil Age	hrs	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status				SEVERE	SEVERE	SEVERE
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185m	>20	334	2 40	▲ 163
Chromium	ppm	ASTM D5185m	>20	▲ 65	11	8
Nickel	ppm	ASTM D5185m	>20	201	4 0	▲ 32
Titanium	ppm	ASTM D5185m		0	0	0
Silver	ppm	ASTM D5185m		0	0	0
Aluminum	ppm	ASTM D5185m	>20	458	1 8	1 4
Lead	ppm	ASTM D5185m	>20	0	0	0
Copper	ppm	ASTM D5185m	>20	20	10	10
Tin	ppm	ASTM D5185m	>20	0	0	0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	0	0
ADDITIVES		method	limit/base	current	history1	history2
Boron	ppm	ASTM D5185m		4	0	0
Barium	ppm	ASTM D5185m		49	73	86
Molybdenum	ppm	ASTM D5185m		9	<1	0
Manganese	ppm	ASTM D5185m		5	6	4
Magnesium	ppm	ASTM D5185m		0	4	2
Calcium	ppm	ASTM D5185m		28	38	44
Phosphorus	ppm	ASTM D5185m		317	281	250
Zinc	ppm	ASTM D5185m		67	23	23
Sulfur	ppm	ASTM D5185m		22574	21186	21855
CONTAMINANT	S	method	limit/base	current	history1	history2
Silicon	ppm	ASTM D5185m	>15	292	▲ 32	△ 29
Sodium	ppm	ASTM D5185m		87	94	73
Potassium	ppm	ASTM D5185m	>20	13	8	4
Water	%	ASTM D6304	>2	0.138	0.365	0.216
ppm Water	ppm	ASTM D6304		1380	3650	2160
FLUID DEGRAD	ATION	method	limit/base	current	history1	history2
A	1/011/	10T11 D0015		0.00		

0.98

Acid Number (AN)


mg KOH/g ASTM D8045

0.38

0.38



OIL ANALYSIS REPORT







Certificate 12367

Laboratory Sample No.

Lab Number : 06236098 Unique Number : 11124932

: WC0892348

Received Tested

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

: 15 Jul 2024 : 16 Jul 2024

Diagnosed : 17 Jul 2024 - Don Baldridge Test Package : IND 2 (Additional Tests: KF)

To discuss this sample report, contact Customer Service at 1-800-237-1369. st - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Contact: DOUG WEIR Doug.Weir@ipaper.com;jon.fazenbaker@wearcheck.com T: (252)633-7350

1785 Weyerhaeuser Road

VANCEBORO, NC

F: (252)633-7761

US 28586

Report Id: WEYNEW [WUSCAR] 06236098 (Generated: 07/17/2024 11:29:36) Rev: 1

Contact/Location: DOUG WEIR - WEYNEW