


## **OIL ANALYSIS REPORT**

Sample Rating Trend





TBN Machine Id TBN-QC10


Component
Oil
Fluid
{not provided} (--- GAL)

DIAGNOSIS

| SAMPLE INFORM | MOITAN | method      | limit/base | current     | history1    | history2    |
|---------------|--------|-------------|------------|-------------|-------------|-------------|
| Sample Date   |        | Client Info |            | 22 Mar 2023 | 21 Mar 2023 | 21 Mar 2023 |
| Machine Age   | HR     | Client Info |            | 0           | 0           | 0           |
| Oil Age       | HR     | Client Info |            | 0           | 0           | 0           |
| Oil Changed   |        | Client Info |            | N/A         | N/A         | N/A         |
| Sample Status |        |             |            | NORMAL      | NORMAL      | NORMAL      |
| SAMPLE IMAGES | ;      | method      | limit/base | current     | history1    | history2    |
| Color         |        |             |            | no image    | no image    | no image    |
| Bottom        |        |             |            | no image    | no image    | no image    |



## **OIL ANALYSIS REPORT**





Certificate L2367

Laboratory Sample No. Lab Number Test Package : TEST

Unique Number : 15893393

: Q0004GEP

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 06 Jun 2023 Received

Diagnosed : 02 Oct 2023 Diagnostician : System

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)