


OIL ANALYSIS REPORT



111 Cooper St. Ch#1B [11582] CARRIER 3508Q16363(B)
Component
Chiller

{not provided} (--- GAL)





Recommendation

The test results indicate normal wear patterns for this type of unit with moisture and acidity in the acceptable range. The elevated moisture is associated with synthetic oils.

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Number		Client Info		GTT11582	GTT11583	
Sample Date		Client Info		20 Sep 2013	28 Feb 2012	
Oil Changed		Client Info		N/A	N/A	
Sample Status				NORMAL	NORMAL	
WEAR METALS		method	limit/base	current	history1	history2
Iron	ppm	ASTM D5185(m)		<1	<1	
Chromium	ppm	ASTM D5185(m)		<1	<1	
Aluminum	ppm	ASTM D5185(m)		<1	<1	
Lead	ppm	ASTM D5185(m)		<1	<1	
Copper	ppm	ASTM D5185(m)		<1	<1	
Tin	ppm	ASTM D5185(m)		<1	<1	
ADDITIVES		method	limit/base	current	history1	history2
Zinc	ppm	ASTM D5185(m)		<1	<1	
CONTAMINANTS		method	limit/base	current	history1	history2
ppm Water	ppm	ASTM D6304*		372	149	
FLUID DEGRADA	TION	method	limit/base	current	history1	history2
Acid Number (AN)	mg KOH/g	ASTM D974*		0.031	0.032	
SAMPLE IMAGES	;	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



OIL ANALYSIS REPORT



Sample No. : GTT11582 Received : 27 Sep 2013 Lab Number : 20131529 Tested : 20 Nov 2013 Diagnosed Unique Number : 15923922 : 21 Nov 2013 - Wes Davis

Test Package : IND 2 (Additional Tests: ICP, KF, TAN Auto)

To discuss this sample report, contact Customer Service at 1-905-847-9300 Ext 26. Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.

Damages: Seller shall in no event be liable for special, incidental, or consequential damages, of a commercial nature, resulting from any cause.

Contact/Location: Tina Coverly - GTTMIS

Report Id: GTTMIS [GTTMIS] 20131529 (Generated: 04/10/2024 08:41:55) Rev: 1

T:

F:

GTT Onset

5629 McAdam Road

Contact: Tina Coverly

tina@gttonset.com

Mississauga, ON

CA L4Z 1N9