

# **OIL ANALYSIS REPORT**

### Sample Rating Trend



# Area TBN TBN-QC10 Component **Oil** Fluid {not provided} (--- GAL)

### DIAGNOSIS


	Ш		 				Т.		л	Ι.				u	л	L	L			U	5
		44	 	 	 	2.		 			-	2	2					4	÷	2.	2
1																					
1 I I I																					
Le u u u																					
1.1																					
2.1.1																					
1.1.1.1																					
5 1 1																					



SAMPLE INFORM	method	limit/base	current	history 1	history 2	
Sample Date		Client Info		05 Jul 2023	05 Jul 2023	03 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	\$	method	limit/base	current	history 1	history 2
Color				no image	no image	no image
Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 06 Jul 2023 501 Madison Ave Lab Number : Q0004HAT Diagnosed : 06 Jul 2023 Cary, NC Unique Number : 16000824 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Report Id: WEACARQA [WUSCAR] Q0004HAT (Generated: 07/06/2023 07:38:19) Rev: 1

Contact/Location: WCLS CARY NC ? - WEACARQA