

## **OIL ANALYSIS REPORT**

#### Sample Rating Trend



# Area PrtCount APC-2-PCS

Component Oil Fluid {not provided} (--- GAL)

### DIAGNOSIS

	11	1	11	1		n	1	Τ	Т	1	I			۵				1
0.000																		
1																		
1.1.1.1																		




#### Jun2023

SAMPLE INFORM	IATION	method	limit/base	current	history 1	history 2
Sample Date		Client Info		06 Jul 2023	05 Jul 2023	05 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	\$	method	limit/base	current	history 1	history 2
Color				no image	no image	no image
Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory Sample No. Received : 06 Jul 2023 501 Madison Ave Lab Number : Q0004HC1 Diagnosed : 06 Jul 2023 Cary, NC Unique Number : 16000979 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA