

# **OIL ANALYSIS REPORT**

### Sample Rating Trend



-3022 bis-3022 bis-3022 bis-3022 bis-2022 bis-2022 bis-2022 bis-3022 bis-30





# TAN Auto Machine Id AutoTAN-1-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history 1	history 2
Sample Date		Client Info		06 Jul 2023	05 Jul 2023	05 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES		method	limit/base	current	history 1	history 2

SAMPLE IMAGES	method	limit/base	current	history 1	history 2
Color			no image	no image	no image
Bottom			no image	no image	no image



## **OIL ANALYSIS REPORT**

#### **GRAPHS**







Laboratory Sample No. Lab Number

: Q0004HC7 Unique Number : 16001008 Test Package : TEST

-0.4

-0.8

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 07 Jul 2023 Received

Diagnosed : 07 Jul 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)