


## **OIL ANALYSIS REPORT**

#### T San







# TAN Auto Machine Id AutoTAN-2-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		12 Jul 2023	12 Jul 2023	11 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						


SAMPLE IMAGE	S	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image




### **OIL ANALYSIS REPORT**

#### **GRAPHS**









Laboratory Sample No.

Lab Number Unique Number : 16001696

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed : Q0004HFM

Test Package : TEST

: 13 Jul 2023

: 13 Jul 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)