

# **OIL ANALYSIS REPORT**

TAN Auto AutoTAN-2-QC

Component **Oil** Fluid

{not provided} (--- GAL)

-3022 Lu7022 Lu7022 Lu7022 Lu7022 Lu7023 Lu7023 Lu7023

Sample Rating Trend



DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		28 Jul 2023	28 Jul 2023	27 Jul 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image




## **OIL ANALYSIS REPORT**


## **GRAPHS**







### Viscosity @ 40°C





Laboratory Sample No. Lab Number

Unique Number : 16004903 Test Package : TEST

: Q0004HOJ

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 31 Jul 2023

Diagnosed : 31 Jul 2023

Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

F: (919)379-4050

Contact: WCLS CARY NC

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)