


### **OIL ANALYSIS REPORT**

Bottom

#### DT Sa







# TAN Auto Machine Id AutoTAN-2-QC

Component **Oil** Fluid

{not provided} (--- GAL)

#### DIAGNOSIS

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		07 Aug 2023	07 Aug 2023	04 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image

no image


no image

no image




#### **OIL ANALYSIS REPORT**


#### **GRAPHS**







## Viscosity @ 40°C





Certificate L2367

Laboratory Sample No. Lab Number

: Q0004HTI Unique Number : 16007848 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 08 Aug 2023

Diagnosed : 08 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050