


# **OIL ANALYSIS REPORT**

## Sample Rating Trend





TAN Auto
Machine Id
AutoTAN-1-QC

Component **Oil** Fluid

{not provided} (--- GAL)

### DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		08 Aug 2023	07 Aug 2023	07 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

SAMPLE IMAGE	S	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image




# **OIL ANALYSIS REPORT**


### **GRAPHS**



#### Non-ferrous Metals



#### Viscosity @ 40°C





Laboratory Sample No. Lab Number Unique Number : 16007976

: Q0004HU4 Test Package : TEST

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 09 Aug 2023

Diagnosed : 09 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

F: (919)379-4050

Contact: WCLS CARY NC

T: (919)379-4102

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)