


OIL ANALYSIS REPORT

TOT







TAN Auto Machine Id AutoTAN-1-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORM	MATION	method	limit/base	current	history1	history2
Sample Date		Client Info		11 Aug 2023	11 Aug 2023	10 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2

SAMPLE IMAGES	method	imit/base	current	nistory i	nistoryz
Color			no image	no image	no image
Bottom			no image	no image	no image




OIL ANALYSIS REPORT


GRAPHS







Viscosity @ 40°C





Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16009047 Test Package : TEST

: Q0004HWV

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 14 Aug 2023

Diagnosed : 14 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050 Contact/Location: WCLS CARY NC? - WEACARQA