


## **OIL ANALYSIS REPORT**

## Sample Rating Trend





TAN Auto
Machine Id
AutoTAN-1-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		22 Aug 2023	21 Aug 2023	21 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image



## **OIL ANALYSIS REPORT**

## **GRAPHS**







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16010594 Test Package : TEST

cSt (40°C) -0.2 -0.4

-0.8

: Q0004I7B

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 23 Aug 2023 Diagnosed : 23 Aug 2023

Diagnostician : Wes Davis

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: (919)379-4102 F: (919)379-4050