

OIL ANALYSIS REPORT

Bottom

TAN Auto AutoTAN-2-QC

Component **Oil** Fluid

{not provided} (--- GAL)

n7023 Aun7023 Aun7023

Sample Rating Trend



no image

no image

DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		24 Aug 2023	24 Aug 2023	23 Aug 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image

no image



OIL ANALYSIS REPORT

GRAPHS







Laboratory Sample No. Lab Number Unique Number : 16010853 Test Package : TEST

: Q0004I92

-0.8

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 25 Aug 2023 Diagnosed

: 25 Aug 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050

Contact/Location: WCLS CARY NC? - WEACARQA