

## **OIL ANALYSIS REPORT**

TAN Auto AutoTAN-2-QC

Component **Oil** Fluid

{not provided} (--- GAL)

-2022 0-2022 0-2022 0-2022 0-2022 0-2022 0-2023

Sample Rating Trend



DIAGNOSIS


SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		21 Oct 2023	20 Oct 2023	19 Oct 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						

SAMPLE IMAGES	method	limit/base	current	history1	history2	
Color			no image	no image	no image	
Bottom			no image	no image	no image	




## **OIL ANALYSIS REPORT**


## **GRAPHS**







## Viscosity @ 40°C 0.8





Certificate L2367

Laboratory Sample No. Lab Number Test Package : TEST

: Q0004K26 Unique Number : 16035449

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 23 Oct 2023

Diagnosed : 23 Oct 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050