

## **OIL ANALYSIS REPORT**

### Sample Rating Trend



# TAN Auto Machine Id AutoTAN-1-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

SAMPLE INFORMATION		method	limit/base	current	history1	history2
Sample Date		Client Info		30 Oct 2023	27 Oct 2023	27 Oct 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2


-2022 0-2022 0-2022 0-2022 0-2022 0-2022 0-2023

SAMPLE IMAGES	method	limit/base	current	history1	history2
Color			no image	no image	no image
Bottom			no image	no image	no image




### **OIL ANALYSIS REPORT**


#### **GRAPHS**







#### Viscosity @ 40°C







Certificate L2367

Laboratory Sample No. Lab Number Unique Number : 16037719 Test Package : TEST

: Q0004KJK

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 30 Oct 2023

Diagnosed : 30 Oct 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

T: (919)379-4102

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

F: (919)379-4050 Contact/Location: WCLS CARY NC? - WEACARQA