


## **OIL ANALYSIS REPORT**

Bottom

Sample Rating Trend



no image

no image

ICP ARCOS-1-S-21/50

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS


| SAMPLE INFORMATION |    | method      | limit/base | current     | history1    | history2    |
|--------------------|----|-------------|------------|-------------|-------------|-------------|
| Sample Date        |    | Client Info |            | 02 Nov 2023 | 02 Nov 2023 | 02 Nov 2023 |
| Machine Age        | HR | Client Info |            | 0           | 0           | 0           |
| Oil Age            | HR | Client Info |            | 0           | 0           | 0           |
| Oil Changed        |    | Client Info |            | N/A         | N/A         | N/A         |
| Sample Status      |    |             |            |             |             |             |
| SAMPLE IMAGES      |    | method      | limit/base | current     | history1    | history2    |
|                    |    |             |            |             |             |             |
| Color              |    |             |            | no image    | no image    | no image    |


no image



## **OIL ANALYSIS REPORT**

## **GRAPHS**







Certificate L2367

Laboratory Sample No. Lab Number

Unique Number : 16039136 Test Package : TEST

: Q0004KTJ

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received : 02 Nov 2023

Diagnosed : 02 Nov 2023 Diagnostician : Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT

501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050