

# **OIL ANALYSIS REPORT**

#### Sample Rating Trend



### Area Machine Id ARCOS-2-AM/900 Component Oil Fluid {not provided} (--- GAL)

DIAGNOSIS




### v2023 Nov2023 Nov2023 Nov2023 Nov2023 Nov2023 Nov2023 Nov2023 Nov2023

SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		03 Nov 2023	03 Nov 2023	03 Nov 2023
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
SAMPLE IMAGES	3	method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image



## **OIL ANALYSIS REPORT**



: WearCheck USA - 501 Madison Ave., Cary, NC 27513 WEARCHECK LUBRICATION SERVICES QA ACCOUNT Laboratory : 06 Nov 2023 Sample No. Received 501 Madison Ave Lab Number : Q0004KXQ Diagnosed : 06 Nov 2023 Cary, NC Unique Number : 16039642 Diagnostician : Wes Davis US 27513 Test Package : TEST Contact: WCLS CARY NC Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369. \* - Denotes test methods that are outside of the ISO 17025 scope of accreditation. T: (919)379-4102 F: (919)379-4050

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

Contact/Location: WCLS CARY NC ? - WEACARQA