

## **OIL ANALYSIS REPORT**

## Sample Rating Trend



TAN Man
Machine Id
TANMAN-QC

Component **Oil** Fluid

{not provided} (--- GAL)

DIAGNOSIS

		72024 160202	4 F602024 F602024	P802024 P802024 P802024 P	02024	
SAMPLE INFORM	IATION	method	limit/base	current	history1	history2
Sample Date		Client Info		01 Feb 2024	01 Feb 2024	01 Feb 2024
Machine Age	HR	Client Info		0	0	0
Oil Age	HR	Client Info		0	0	0
Oil Changed		Client Info		N/A	N/A	N/A
Sample Status						
CONTAMINATION	J	method	limit/base	current	history1	history2
Water		WC Method		NEG	NEG	NEG
SAMPLE IMAGES		method	limit/base	current	history1	history2
Color				no image	no image	no image
Bottom				no image	no image	no image

3074 E457074 E457074 E457074 E457074 E457074 E457074 E457074



## **OIL ANALYSIS REPORT**

**GRAPHS** 



Laboratory Sample No.

Lab Number : Q0005B5U **Unique Number** : 16089172

Received Tested

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 : 01 Feb 2024

: 01 Feb 2024 Diagnosed : 01 Feb 2024 - Wes Davis

WEARCHECK LUBRICATION SERVICES QA ACCOUNT 501 Madison Ave Cary, NC US 27513

Contact: WCLS CARY NC

Test Package : TEST Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

\* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

T: (919)379-4102 Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012) F: (919)379-4050

Contact/Location: WCLS CARY NC ? - WEACARQA

Report Id: WEACARQA [WUSCAR] Q0005B5U (Generated: 02/08/2024 22:53:09) Rev: 1