

PROBLEM SUMMARY

Sample Rating Trend

ISO


Machine Id **5804533 (S/N 1316)**

Component

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS										
Sample Status			ABNORMAL	ABNORMAL						
Particles >6µm	ASTM D7647	>1300	4157	105						
Particles >14µm	ASTM D7647	>80	277	7						
Particles >21µm	ASTM D7647	>20	△ 35	2						
Oil Cleanliness	ISO 4406 (c)	>/17/13	2 1/19/15	14/10						

Customer Id: GMAOAK Sample No.: KCP51982 Lab Number: 05632383 Test Package: IND 2

To manage this report scan the QR code

To discuss the diagnosis or test data:

Don Baldridge +1 don.b505@comcast.net

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS							
Action	Status	Date	Done By	Description			
Change Fluid			?	Oil and filter change at the time of sampling has been noted.			
Change Filter			?	Oil and filter change at the time of sampling has been noted.			

HISTORICAL DIAGNOSIS

01 Jul 2021 Diag: Jonathan Hester

VISCOSITY




Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The amount and size of particulates present in the system are acceptable. The oil viscosity is higher than normal. The AN level is acceptable for this fluid.





OIL ANALYSIS REPORT

Sample Rating Trend



ISO



5804533 (S/N 1316)

Compressor

KAESER SIGMA (OEM) M-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a high amount of particulates present in the oil.


Fluid Condition


The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

			Jul2021	Aug2022		
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KCP51982	KCP33693	
Sample Date				11 Aug 2022	01 Jul 2021	
Machine Age	hrs			24796	19973	
Oil Age	hrs			3000	4300	
Oil Changed				Changed	Changed	
Sample Status				ABNORMAL	ABNORMAL	
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	0	<1	
Chromium	ppm	ASTM D5185m	>10	0	0	
Nickel	ppm	ASTM D5185m	>3	0	<1	
Titanium	ppm	ASTM D5185m	>3	0	0	
Silver	ppm	ASTM D5185m	>2	0	<1	
Aluminum	ppm	ASTM D5185m	>10	1	<1	
Lead	ppm	ASTM D5185m	>10	0	<1	
Copper	ppm	ASTM D5185m	>50	3	5	
Tin	ppm	ASTM D5185m	>10	<1	<1	
Antimony	ppm	ASTM D5185m			<1	
Vanadium	ppm	ASTM D5185m		0	0	
Cadmium	ppm	ASTM D5185m		0	<1	
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m	0	0	35	
Barium	ppm	ASTM D5185m	90	22	0	
Molybdenum	ppm	ASTM D5185m	0	0	0	
Manganese	ppm	ASTM D5185m		0	0	
Magnesium	ppm	ASTM D5185m	100	66	26	
Calcium	ppm	ASTM D5185m	0	<1	0	
Phosphorus	ppm	ASTM D5185m	0	3	13	
Zinc	ppm	ASTM D5185m	0	0	15	
Sulfur	ppm	ASTM D5185m	23500	20779	20027	
CONTAMINANTS		method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	2	10	
Sodium	ppm	ASTM D5185m		7	6	
Potassium	ppm	ASTM D5185m	>20	2	<1	
Water	%	ASTM D6304	>0.05	0.027	0.007	
ppm Water	ppm	ASTM D6304	>500	274.8	71.5	
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4µm		ASTM D7647		11806	503	
Particles >6µm		ASTM D7647	>1300	4157	105	
Particles >14µm		ASTM D7647	>80	<u> </u>	7	
Particles >21µm		ASTM D7647	>20	4 35	2	
Particles >38µm		ASTM D7647	>4	1	0	
Particles >71μm		ASTM D7647	>3	0	0	
Oil Cleanliness		ISO 4406 (c)	>/17/13	<u>21/19/15</u>	14/10	
FLUID DEGRADA	TION	method	limit/base	current	history 1	history 2



OIL ANALYSIS REPORT





120

(B) 1.20 0.96 € 0.72 은 0.48

> 0.24 0.00

1/22





Laboratory Sample No.

Lab Number **Unique Number**

: KCP51982 : 05632383

40

: 10116904

Viscosity @ 40°C

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received Diagnosed

: 01 Sep 2022 : 03 Sep 2022 Diagnostician : Don Baldridge

Acid Number

9824 KITTY LN OAKLAND, CA USA 94603 Contact: Service Manager

GM ASSICIATES

Test Package : IND 2 (Additional Tests: KF, PrtCount) Certificate L2367 To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T: F: