

PROBLEM SUMMARY

Sample Rating Trend




KAESER 7955456

Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

COMPONENT CONDITION SUMMARY



RECOMMENDATION

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

PROBLEMATIC TEST RESULTS							
Sample Status			ATTENTION	ABNORMAL	ABNORMAL		
Particles >14μm	ASTM D7647	>80	<u></u> ▲ 85	<u>^</u> 201			
Oil Cleanliness	ISO 4406 (c)	>/17/13	19/17/14	2 0/18/15			

Customer Id: RYOSHEKC Sample No.: KC102648 Lab Number: 05648920 Test Package: IND 2



To manage this report scan the QR code

To discuss the diagnosis or test data: Angela Borella +1 800-237-1369 angela.borella@wearcheckusa.com

To change component or sample information: Customer Service +1 1-800-237-1369 customerservice@wearcheck.com

RECOMMENDED ACTIONS

There are no recommended actions for this sample.

HISTORICAL DIAGNOSIS

09 May 2022 Diag: Don Baldridge

ISO



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a high amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.



17 Jan 2022 Diag: Doug Bogart

VIS DEBRIS



No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. We were unable to perform a particle count due to a high concentration of particles present in this sample. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.



09 Sep 2021 Diag: Don Baldridge

ISO




Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is a moderate amount of particulates present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.





OIL ANALYSIS REPORT



ISO

KAESER 7955456 Component

Compressor

KAESER SIGMA (OEM) S-460 (--- GAL)

DIAGNOSIS

Recommendation

No corrective action is recommended at this time. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.

Wear

All component wear rates are normal.

Contamination

There is a moderate amount of particulates present in the oil.


Fluid Condition

The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.


		Sep202	1 Jan 2022	May2022 S	ep 2022	
SAMPLE INFORM	MATION	method	limit/base	current	history 1	history 2
Sample Number				KC102648	KC97208	KC91186
Sample Date				15 Sep 2022	09 May 2022	17 Jan 2022
Machine Age	hrs			8818	6176	3881
Oil Age	hrs			0	0	2000
Oil Changed				Not Changd	Not Changd	Not Changd
Sample Status				ATTENTION	ABNORMAL	ABNORMAL
WEAR METALS		method	limit/base	current	history 1	history 2
Iron	ppm	ASTM D5185m	>50	<1	<1	1
Chromium	ppm	ASTM D5185m	>10	0	0	0
Nickel	ppm	ASTM D5185m	>3	0	<1	0
Titanium	ppm	ASTM D5185m	>3	0	0	0
Silver	ppm	ASTM D5185m	>2	<1	<1	0
Aluminum	ppm	ASTM D5185m	>10	0	0	<1
Lead	ppm	ASTM D5185m	>10	<1	0	0
Copper	ppm	ASTM D5185m	>50	23	16	5
Tin	ppm	ASTM D5185m	>10	0	<1	<1
Antimony	ppm	ASTM D5185m				0
Vanadium	ppm	ASTM D5185m		0	0	0
Cadmium	ppm	ASTM D5185m		<1	<1	<1
ADDITIVES		method	limit/base	current	history 1	history 2
Boron	ppm	ASTM D5185m		0	0	0
Barium	ppm	ASTM D5185m	90	0	0	19
Molybdenum	ppm	ASTM D5185m		0	0	0
Manganese	ppm	ASTM D5185m		0	0	<1
Magnesium	ppm	ASTM D5185m	90	2	9	63
Calcium	ppm	ASTM D5185m	2	0	0	2
Phosphorus	ppm	ASTM D5185m		12	2	3
Zinc	ppm	ASTM D5185m		51	27	23
CONTAMINANTS	i	method	limit/base	current	history 1	history 2
Silicon	ppm	ASTM D5185m	>25	24	13	7
Sodium	ppm	ASTM D5185m		1	4	27
Potassium	ppm	ASTM D5185m	>20	<1	0	5
Water	%	ASTM D6304	>0.05	0.017	0.005	0.007
ppm Water	ppm	ASTM D6304	>500	175.9	51.6	79.4
FLUID CLEANLIN	IESS	method	limit/base	current	history 1	history 2
Particles >4µm		ASTM D7647		2757	9862	
Particles >6µm		ASTM D7647	>1300	1085	2439	
Particles >14μm		ASTM D7647	>80	<u>▲</u> 85	2 01	
Particles >21µm		ASTM D7647	>20	17	△ 39	
Particles >38μm		ASTM D7647	>4	1	<u>^</u> 6	
Particles >71μm		ASTM D7647	>3	0	0	
Oil Cleanliness		ISO 4406 (c)	>/17/13	<u> </u>	△ 20/18/15	
FLUID DEGRADA	TION	method	limit/base	current	history 1	history 2
Acid Number (AN)	mg KOH/g	ASTM D8045	0.4	0.38	0.43	0.34



OIL ANALYSIS REPORT



1001141						
VISUAL		method	limit/base	current	history 1	history 2
White Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Yellow Metal	scalar	*Visual	NONE	NONE	NONE	NONE
Precipitate	scalar	*Visual	NONE	NONE	NONE	NONE
Silt	scalar	*Visual	NONE	NONE	NONE	NONE
Debris	scalar	*Visual	NONE	NONE	LIGHT	▲ MODER
Sand/Dirt	scalar	*Visual	NONE	NONE	NONE	NONE
Appearance	scalar	*Visual	NORML	NORML	NORML	NORML
Odor	scalar	*Visual	NORML	NORML	NORML	NORML
Emulsified Water	scalar	*Visual	>0.05	NEG	NEG	NEG
Free Water	scalar	*Visual		NEG	NEG	NEG
FLUID PROPERT	ΓIES	method	limit/base	current	history 1	history 2
Visc @ 40°C	cSt	ASTM D445	46	44.3	44.4	44.5
SAMPLE IMAGES	S	method	limit/base	current	history 1	history 2
Color						
Bottom						







Certificate L2367

Laboratory Sample No. Lab Number

Test Package : IND 2

: KC102648 : 05648920 Unique Number : 10143459

: WearCheck USA - 501 Madison Ave., Cary, NC 27513 Received

Diagnosed

: 22 Sep 2022 : 26 Sep 2022 Diagnostician : Angela Borella

RYOBI DIE CASTING 800 W MAUSOLEUM RD SHELBYVILLE, IN USA 46176

Contact: Service Manager

To discuss this sample report, contact Customer Service at 1-800-237-1369.

* - Denotes test methods that are outside of the ISO 17025 scope of accreditation.

Statements of conformity to specifications are based on the simple acceptance decision rule (JCGM 106:2012)

T:

F: