



SAMPLE SUBMISSION FORM

Oil Analysis Laboratories

501 Madison Avenue C8-1175 Appleby Line
 Cary, NC 27513 Burlington, ON L7L 5H9
 USA CANADA
 1-800-237-1369 1-800-268-2131
 (919) 379-4102 (905) 569-8600
 Fax (919) 379-4050 Fax (905) 569-8605

WEARCHECK sample kits will be replaced with unused kits if defective in manufacture, labeling, or packaging, or if lost by us or any associate company even though by negligence or other fault.

WEARCHECK shall not be liable or responsible for the future performance or failure of any engine, piece of equipment or material involved in any test or sample. The Company makes no warranties, representations, or guaranties with respect to the performance of any such engine, piece of equipment, or material.

NOTE 1: For sample identification, please ensure that you either print labels and place on the sample bottle or that you label the sample cap with the reference number (*Label) shown below.

NOTE 2: Please attach 7 Sample Information Forms (SIFs) as proof of payment for these analysis.

Shipping Info







Shipped Via:
 Tracking Number:
 Shipped On:
 Submitted By: BILL BUTLER [Oil Filtration Solutions Ltd.]

SAMPLING INSTRUCTIONS AND PRECAUTIONS

For best results we suggest the following precautions when taking the sample.

INSTRUCTIONS FOR TAKING SAMPLE - the SAMPLE should not be taken MORE THAN 30 MINUTES after shutdown, and the oil should have been in service for at least 10 hours or 500 miles, before the oil can accurately reflect wear conditions. AVOID CONTAMINATION OF THE SAMPLE - Clean around the drain plug before draining. Remove the drain, and when about half the oil has run out, catch the sample by inserting the bottle into the oil stream. The bottle should be at least 3/4 filled. Do not remove the bottle cap until you are ready to take the sample, and recap the bottle immediately after filling. Take care not to confuse samples from different units. Or, remove sample with a suction pump by inserting the siphon tube down the dipstick tube or into the sump/reservoir. The siphon tube must be clean by either replacement or rinsing with a solvent and drying. Do not rinse with gasoline or diesel fuel. Or, Engines with sample ports (i.e. gauge plugs, probalizer mini-plugs), follow the specific instructions pertaining to the sampling device purchased.

Oil Filtration Solutions Ltd.

	*Label : 405922	Area	MARINE HARVESTERS LTD	Machine Age	: 33563.0
	Sample Number : OF0000845	Machine Id	FISHING VESSEL MV JACOB LOUISA	Fluid Age	: 520.0
	Test Package : MOB 2	Component	KUBOTA V3300-T 6W1148 1 Genset	Filter Age	: 520.0
	Sample Date : 10/16/2023	Fluid	TOTAL FINA RUBIA TIR 7900 15W40 (16 LTR)	Fluid Maintenance	: Changed
				Filter Maintenance	: Changed
	*Label : 405923	Area	MARINE HARVESTERS LTD	Machine Age	: 9652.0
	Sample Number : OF0000846	Machine Id	FISHING VESSEL MV JACOB LOUISA	Fluid Age	: 248.0
	Test Package : MOB 2	Component	JOHN DEERE 40457FM50 CD4045C020672 2 Genset	Filter Age	: 248.0
	Sample Date : 10/16/2023	Fluid	TOTAL FINA RUBIA TIR 7900 15W40 (16 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd
	*Label : 405924	Area	MARINE HARVESTERS LTD	Machine Age	: 3850.0
	Sample Number : OF0000848	Machine Id	FISHING VESSEL MV JACOB LOUISA	Fluid Age	: 3850.0
	Test Package : MOB 2	Component	MVJLHS Hydraulic System	Filter Age	: 50.0
	Sample Date : 10/16/2023	Fluid	AW HYDRAULIC OIL ISO 32 (2000 LTR)	Fluid Maintenance	: Not Not Changd
				Filter Maintenance	: Changed
	*Label : 405926	Area	MARINE HARVESTERS LTD	Machine Age	: 30695.0
	Sample Number : OF0000851	Machine Id	FISHING VESSEL MV JACOB LOUISA	Fluid Age	: 1186.0
	Test Package : MOB 2	Component	MITSUBISHI S6R-Y3MPTAW-1 19637 Main Engine	Filter Age	: 186.0
	Sample Date : 07/07/2023	Fluid	TOTAL FINA RUBIA TIR 7900 15W40 (1440 LTR)	Fluid Maintenance	: Changed
				Filter Maintenance	: Changed
	*Label : 405927	Area	MARINE HARVESTERS LTD	Machine Age	: 31218.0
	Sample Number : OF0000844	Machine Id	FISHING VESSEL MV JACOB LOUISA	Fluid Age	: 1709.0
	Test Package : MOB 2	Component	TWIN DISC MVJLT Transmission	Filter Age	: 523.0
	Sample Date : 10/16/2023	Fluid	TOTAL DYNATRANS AC 30 (25 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd
	*Label : 406139	Area	MARINE HARVESTERS LTD	Machine Age	: 34434.0
	Sample Number : OF0000847	Machine Id	FISHING VESSEL MV JACOB LOUISA	Fluid Age	: 510.0
	Test Package : MOB 2	Component	KUBOTA V3300-T 6W1148 1 Genset	Filter Age	: 510.0
	Sample Date : 09/20/2023	Fluid	TOTAL FINA RUBIA TIR 7900 15W40 (16 LTR)	Fluid Maintenance	: Not Changd
				Filter Maintenance	: Not Changd



*Label : 406140
Sample Number : OF0000849
Test Package : MOB 2
Sample Date : 10/16/2023

Area : MARINE HARVESTERS LTD
Machine Id : FISHING VESSEL MV JACOB LOUISA
Component : MVJLHS Hydraulic System
Fluid : AW HYDRAULIC OIL ISO 32 (2000 LTR)

Machine Age : 3950.0
Fluid Age : 3950.0
Filter Age : 100.0
Fluid Maintenance : Not Changd
Filter Maintenance : Changed