MOB I

WEAR CHECK

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Area
RAY JONES
Machine Id
VV088685
Component
Right Diesel Engine
Fluid
VOLVO VDS-4.5 Premium Motor Oil 15W40 (--- GAL)

RECOMMENDATION

Confirm the source of the lubricant being utilized for top-up/fill.
Resample at the next service interval to monitor.

WEAR

Metal levels are typical for a components first oil change.

CONTAMINATION

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.

FLUID CONDITION

Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		WC0847280	---	---
Sample Date		Client Info		01 Nov 2023	---	---
Machine Age	hrs	Client Info		583	---	---
Oil Age	hrs	Client Info		583	---	---
Filter Age	hrs	Client Info		583	---	---
Oil Changed		Client Info		Changed	---	---
Filter Changed		Client Info		Changed	---	---
Sample Status				NORMAL	---	---
Iron	ppm	ASTM D5185(m)	>80	24	---	---
Chromium	ppm	ASTM D5185(m)	>6	<1	---	---
Nickel	ppm	ASTM D5185(m)	>2	1	---	---
Titanium	ppm	ASTM D5185(m)	>2	0	---	---
Silver	ppm	ASTM D5185(m)	>2	0	---	---
Aluminum	ppm	ASTM D5185(m)	>20	2	---	---
Lead	ppm	ASTM D5185(m)	>95	1	---	---
Copper	ppm	ASTM D5185(m)	>85	9	---	---
Tin	ppm	ASTM D5185(m)	>9	<1	---	---
Vanadium	ppm	ASTM D5185(m)		0	---	---
White Metal	scalar	Visual*	NONE	NONE	---	---
Yellow Metal	scalar	Visual*	NONE	NONE	---	---
Silicon	ppm	ASTM D5185(m)	>25	4	---	---
Potassium	ppm	ASTM D5185(m)	>20	7	---	---
Fuel		WC Method	>4.0	<1.0	---	---
Water		WC Method	>0.1	NEG	---	---
Glycol		WC Method		NEG	---	---
Soot %	%	ASTM D7844*		0.3	---	---
Nitration	Abs/cm	ASTM D7624*	>20	7.2	---	---
Sulfation	Abs/.1mm	ASTM D7415*	>30	20.4	---	---
Silt	scalar	Visual*	NONE	NONE	---	---
Debris	scalar	Visual*	NONE	NONE	---	---
Sand/Dirt	scalar	Visual*	NONE	NONE	---	---
Appearance	scalar	Visual*	NORML	NORML	---	---
Odor	scalar	Visual*	NORML	NORML	---	---
Emulsified Water	scalar	Visual*	>0.1	NEG	---	---
Sodium	ppm	ASTM D5185(m)		3	---	---
Boron	ppm	ASTM D5185(m)		140	---	---
Barium	ppm	ASTM D5185(m)		0	---	---
Molybdenum	ppm	ASTM D5185(m)		3	---	---
Manganese	ppm	ASTM D5185(m)		0	---	---
Magnesium	ppm	ASTM D5185(m)		66	---	---
Calcium	ppm	ASTM D5185(m)		2108	---	---
Phosphorus	ppm	ASTM D5185(m)		981	---	---
Zinc	ppm	ASTM D5185(m)		1104	---	---
Sulfur	ppm	ASTM D5185(m)		3101	---	---
Oxidation	Abs/.1mm	ASTM D7414*	>25	15.8	---	---
Visc @ 100°C	cSt	ASTM D7279(m)		14.3	---	---

Viscosity @ 100°C



Additives



Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Soot %



ISO 17025:2017 Accredited Laboratory

Laboratory	: WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9		
Sample No.	: WC0847280	**Received**	: 15 Feb 2024
Lab Number	: 02615864	**Tested**	: 20 Feb 2024
Unique Number	: 5732974	**Diagnosed**	: 20 Feb 2024 - Kevin Marson
Test Package	: MOB 1 (Additional Tests: Visual)		

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

FMC Marine & The Knotical Shop
373 Barton St
STONEY CREEK, ON
CA L8E 2L8
Contact: Lorrie Gruhl
lgruhl@fmcgroup.ca
T: (905)902-0125
F: