MOBIL LUBE 360™ OIL DIAGNOSTICS

OIL ANALYSIS REPORT

WEAR	NORMAL
CONTAMINATION	NORMAL
FLUID CONDITION	NORMAL

Machine Id
731027
Component
Natural Gas Engine
Fluid
CASTROL 15W40 (--- GAL)

RECOMMENDATION

Resample at the next service interval to monitor.

WEAR

Metal levels are typical for a new component breaking in.

CONTAMINATION

Elevated aluminum (Al) and/or lead (Pb) and potassium (K) levels in your metals analysis are likely a result of solder flux release into the lubricant and is common on new equipment/components. There is no indication of any contamination in the oil.

FLUID CONDITION

The condition of the oil is acceptable for the time in service.

Test	UOM	Method	Limit/Abn	Current	History1	History2
Sample Number		Client Info		**GFL0100752**	GFL0100759	GFL0041636
Sample Date		Client Info		**12 Apr 2024**	01 Dec 2023	02 May 2023
Machine Age	kms	Client Info		**85120**	85120	70772
Oil Age	kms	Client Info		**0**	0	0
Filter Age	kms	Client Info		**0**	0	0
Oil Changed		Client Info		**N/A**	Changed	Changed
Filter Changed		Client Info		**N/A**	N/A	Changed
Sample Status				**NORMAL**	NORMAL	NORMAL
Iron	ppm	ASTM D5185(m)	>50	**14**	17	10
Chromium	ppm	ASTM D5185(m)	>4	**<1**	1	<1
Nickel	ppm	ASTM D5185(m)	>2	**<1**	<1	<1
Titanium	ppm	ASTM D5185(m)		**0**	0	<1
Silver	ppm	ASTM D5185(m)	>3	**0**	<1	0
Aluminum	ppm	ASTM D5185(m)	>9	**5**	4	2
Lead	ppm	ASTM D5185(m)	>30	**<1**	8	2
Copper	ppm	ASTM D5185(m)	>35	**1**	2	1
Tin	ppm	ASTM D5185(m)	>4	**0**	<1	<1
Vanadium	ppm	ASTM D5185(m)		**0**	0	0
Silicon	ppm	ASTM D5185(m)	>+100	**2**	4	3
Potassium	ppm	ASTM D5185(m)	>20	**17**	8	0
Water		WC Method	>0.1	**NEG**	NEG	NEG
Soot %	%	ASTM D7844*		**0**	0	0
Nitration	Abs/cm	ASTM D7624*	>20	**11.0**	12.6	11.3
Sulfation	Abs/.1mm	ASTM D7415*	>30	**22.6**	27.4	24.3
Emulsified Water	scalar	Visual*	>0.1	**NEG**	NEG	NEG
Sodium	ppm	ASTM D5185(m)	>406	**2**	3	2
Boron	ppm	ASTM D5185(m)		**9**	6	8
Barium	ppm	ASTM D5185(m)		**0**	<1	0
Molybdenum	ppm	ASTM D5185(m)		**50**	54	53
Manganese	ppm	ASTM D5185(m)		**<1**	<1	<1
Magnesium	ppm	ASTM D5185(m)		**505**	553	567
Calcium	ppm	ASTM D5185(m)		**1629**	1610	1626
Phosphorus	ppm	ASTM D5185(m)		**684**	718	753
Zinc	ppm	ASTM D5185(m)		**894**	937	931
Sulfur	ppm	ASTM D5185(m)		**1950**	1954	2074
Oxidation	Abs/.1mm	ASTM D7414*	>25	**18.2**	22.9	19.5
Visc @ 100°C	cSt	ASTM D7279(m)		**14.6**	14.6	14.7

FT-IR (Direct Trend)



Viscosity @ 100°C



Iron (ppm)



Lead (ppm)



Aluminum (ppm)



Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 100°C



Additives



ISO 17025:2017 Accredited Laboratory

Laboratory : WearCheck - C8-1175 Appleby Line, Burlington, ON L7L 5H9
Sample No. : GFL0100752
Lab Number : 02629116
Unique Number : 5762248
Test Package : MOB 1

Received : 16 Apr 2024
Tested : 16 Apr 2024
Diagnosed : 17 Apr 2024 - Kevin Marson

To discuss this sample report, contact Customer Service at 1-800-268-2131.
Test denoted (*) outside scope of accreditation, (m) method modified, (e) tested at external lab.
Validity of results and interpretation are based on the sample and information as supplied.

GFL Environmental - 277 - Niagara Regional
C/O Metro Truck Niagara Inc., 411 Glendale Avenue
St. Catharines, ON
CA L2P 3Y1
Contact: Kelly Bremner
kbremner@gflenv.com
T: (437)235-6849
F: